Submit 3 Copies to Appropriate District Office

APTROVED BY-

CONDITIONS OF APPROVAL, IP ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

t	Form C-103 Revised 1-1-89	
	WELL API NO.	
,	5. Indicate Type of Lease STATE FEE X	
	6. State Oil & Gas Lease No.	
A	7. Lease Name or Unit Agreement Name	
	BATES	
	8. Well No.	
	1 9. Pool name or Wildcat	
	JALMAT TANSILL YATES 7 RIVERS	
	1980 Feet From The SOUTH Line	
	NMPM LEA County	
, Report, or Other Data UBSEQUENT REPORT OF:		
	ALTERING CASING	
	BOPNS. PLUG AND ABANDONMENT	
) CE	EMENT JOB L	
inclu	ding estimated date of starting any proposed	
w/	130 SXS CLASS C CMT.	
ASS C CMT.		
AN	D CASING SHOE @ 1165-1390'. USE 40	
7" –	8 1/4" ANNULUS AND 7" CASING	
R AND RESTORE LOCATION.		
I AS	SST DATE 3/31/92	
	TELEPHONE NO. (915)688-6	

OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 Santa Fe, New Mexico 87504-2088 **DISTRICT II** P.O. Drawer DD, Artesia, NM 88210 DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: GAS X WELL OTHER 2. Name of Operator MERIDIAN OIL INC 3. Address of Operator P.O. Box 51810, Midland, TX 79710-1810 4 Well Location 660 Feet From The WEST Line and raship 25S Range 37E

10. Elevation (Show whether DF, RKB, RT, GR, etc.) Township Section 20 3049' GR Check Appropriate Box to Indicate Nature of Notice 11. NOTICE OF INTENTION TO: X PERFORM REMEDIAL WORK PLUG AND ABANDON **REMEDIAL WORK CHANGE PLANS** COMMENCE DRILL TEMPORARILY ABANDON **CASING TEST AND PULL OR ALTER CASING** OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, is work) SEE RULE 1103. NOTIFY OCD PRIOR TO COMMENCING PLUGGING OPERATIONS. SET CEMENT RETAINER @ +/-2575'. SQUEEZE OPEN HOLE UNDER RETAINER Y SPOT CEMENT PLUG ACROSS BASE OF SALT @ 2450-2575'. USE 25 SXS CLA CIRC HOLE W/ 9 PPG GELLED BRINE. SPOT CMT PLUG ACROSS TOP OF SALT SXS CLASS C CMT. PERFORATE 4 SQUEEZE HOLES @ 315'. PUMP CMT FROM SURFACE TO FILL 7 FROM SURFACE TO 315'. USE 75 SXS CLASS C CMT. CUT OFF CASING 3' BELOW GROUND LEVEL AND INSTALL P&A MARKER. CLEA I hereby certify that the information above is true and complete to the best of my knowledge and belief. PRODUCTION SIGNATURE 943 TYPE OR PRINT NAME ROXANN SCHOLZ Orig. Signed by Paul Kautz (This space for State Use) VDB (), Geologist

 $\bigcirc f$

-CLM 11/18/91

MERIDIAN OIL

BATES NO. 1

JALMAT FIELD

LEA COUNTY, NEW MEXICO

PROPOSED CONDITION AFTER P&A

