Submit One Copy To Appropriate District	State of New M	levico	RECV'D 12/9/20	Form C-103	
Office	Energy, Minerals and Nat		Revis	sed November 3, 2011	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, wither all and Iva	diai Resources	WELL API NO.	, 2011	
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATIO	N DIVISION	30-025-3		
District III	1220 South St. Fra	ALL THE PERSON OF THE PERSON O	5. Indicate Type of Lea		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8		STATE  6. State Oil & Gas Leas	FEE	
1220 S. St. Francis Dr., Santa Fe, NM 87505	2		o. State on & Gas Leas	se Ivo.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name MARALO STATE		
PROPOSALS.)  1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other			8. Well Number #2		
2. Name of Operator			9. OGRID Number		
SOUTHWEST ROYALTIES, INC.			21355		
3. Address of Operator P.O. BOX 53570; MIDLAND, TEXAS 79710			10. Pool name or Wildcat EUNICE MONUMENT - GRAYBURG		
4. Well Location					
Unit Letter N : 330	feet from the SOUTH 1	ine and 1650 fee	et from the WEST	line	
Section 28 Township	18S Range 37E N	MPM Count	y LEA		
	11. Elevation (Show whether D.				
12. Check Appropriate Box to I		7' GR Report or Other D	l		
NOTICE OF INT	ENTION TO: PLUG AND ABANDON □	REMEDIAL WORK	SEQUENT REPOR		
	CHANGE PLANS	COMMENCE DRII		RING CASING ☐ '	
<u> </u>	MULTIPLE COMPL	CASING/CEMENT			
OTHER:	П	✓ Location is re	ady for OCD inspection	after DS A	
OTTILIN.		Location is re	ady for OCD inspection	alter F CA	
All pits have been remediated in	compliance with OCD rules and	the terms of the Oper	rator's pit permit and clos	ure plan.	
Rat hole and cellar have been fill	ed and leveled. Cathodic protec	the terms of the Oper	properly abandoned.	ure plan.	
<ul> <li>✓ All pits have been remediated in Ω</li> <li>✓ Rat hole and cellar have been fill ✓</li> <li>✓ A steel marker at least 4" in diam</li> </ul>	ed and leveled. Cathodic protec	the terms of the Oper	properly abandoned.	ure plan.	
Rat hole and cellar have been fille A steel marker at least 4" in diam  OPERATOR NAME, LEAS	ed and leveled. Cathodic protected eter and at least 4' above ground SE NAME, WELL NUMBER,	the terms of the Oper tion holes have been p I level has been set in API NUMBER, QU	properly abandoned. concrete. It shows the  ARTER/QUARTER LO	OCATION OR	
Rat hole and cellar have been fill A steel marker at least 4" in diam  OPERATOR NAME, LEAS UNIT LETTER, SECTION	ed and leveled. Cathodic protecter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE.	the terms of the Oper tion holes have been p I level has been set in API NUMBER, QU All INFORMATIO	properly abandoned. concrete. It shows the  ARTER/QUARTER LO	OCATION OR	
Rat hole and cellar have been fill A steel marker at least 4" in diam  OPERATOR NAME, LEAS UNIT LETTER, SECTION	ed and leveled. Cathodic protected eter and at least 4' above ground SE NAME, WELL NUMBER,	the terms of the Oper tion holes have been p I level has been set in API NUMBER, QU All INFORMATIO	properly abandoned. concrete. It shows the  ARTER/QUARTER LO	OCATION OR	
<ul> <li>Rat hole and cellar have been fille</li> <li>A steel marker at least 4" in diam</li> <li>OPERATOR NAME, LEAS UNIT LETTER, SECTION PERMANENTLY STAMP</li> <li></li></ul>	ed and leveled. Cathodic protecter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUI	the terms of the Oper tion holes have been p il level has been set in API NUMBER, QU All INFORMATIO RFACE.	properly abandoned. concrete. It shows the ARTER/QUARTER LON HAS BEEN WELDE	OCATION OR D OR	
Rat hole and cellar have been fill  A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP  The location has been leveled as a other production equipment.	ed and leveled. Cathodic protecter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUITE MARKER'S SUITE AS POSSIBLE TO ORIGINAL GROUND AS POSSI	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION RFACE.	properly abandoned. concrete. It shows the ARTER/QUARTER LON HAS BEEN WELDE peen cleared of all junk, to	OCATION OR D OR	
<ul> <li>Rat hole and cellar have been fille</li> <li>A steel marker at least 4" in diam</li> <li>OPERATOR NAME, LEAS UNIT LETTER, SECTION PERMANENTLY STAMP</li> <li></li></ul>	ed and leveled. Cathodic protecter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUITED ON T	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION RFACE.	properly abandoned. concrete. It shows the ARTER/QUARTER LON HAS BEEN WELDE been cleared of all junk, to and level.	OCATION OR D OR  Tash, flow lines and	
Rat hole and cellar have been fill  A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP  The location has been leveled as a other production equipment.	ed and leveled. Cathodic protecter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUIT nearly as possible to original ground risers have been cut off at least emaining well on lease, the batter	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALI INFORMATION RFACE.  Sound contour and has but two feet below ground ry and pit location(s)	properly abandoned. concrete. It shows the  ARTER/QUARTER LO DN HAS BEEN WELDE  been cleared of all junk, to and level. have been remediated in	DCATION OR D OR  Tash, flow lines and compliance with	
<ul> <li>✓ Rat hole and cellar have been fille</li> <li>✓ A steel marker at least 4" in diam</li> <li>OPERATOR NAME, LEAS UNIT LETTER, SECTION PERMANENTLY STAMP</li> <li>✓ The location has been leveled as nother production equipment.</li> <li>✓ Anchors, dead men, tie downs and If this is a one-well lease or last reoCD rules and the terms of the Operation lease and well location.</li> </ul>	ed and leveled. Cathodic protecter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUIT the array as possible to original ground risers have been cut off at least emaining well on lease, the batter tor's pit permit and closure plant.	the terms of the Oper tion holes have been purely level has been set in API NUMBER, QUALINFORMATION AND CONTRACE.  Sound contour and has but two feet below ground cry and pit location(s). All flow lines, production to the product of the contract of the c	properly abandoned. concrete. It shows the ARTER/QUARTER LONG HAS BEEN WELDE been cleared of all junk, to the level. have been remediated in action equipment and junication equipment and junication.	DCATION OR D OR  Tash, flow lines and  compliance with k have been removed	
<ul> <li>□ Rat hole and cellar have been fill</li> <li>□ A steel marker at least 4" in diam</li> <li>□ OPERATOR NAME, LEAS</li> <li>□ UNIT LETTER, SECTION</li> <li>□ PERMANENTLY STAMP</li> <li>□ The location has been leveled as a other production equipment.</li> <li>□ Anchors, dead men, tie downs and</li> <li>□ If this is a one-well lease or last rough occupant of the Operation lease and well location.</li> <li>□ All metal bolts and other materials</li> </ul>	ed and leveled. Cathodic protecter and at least 4' above ground SE NAME, WELL NUMBER, TOWNSHIP, AND RANGE. ED ON THE MARKER'S SUIT the array as possible to original ground risers have been cut off at least emaining well on lease, the batter tor's pit permit and closure plant.	the terms of the Oper tion holes have been purely level has been set in API NUMBER, QUALINFORMATION AND CONTRACE.  Sound contour and has but two feet below ground cry and pit location(s). All flow lines, production to the product of the contract of the c	properly abandoned. concrete. It shows the ARTER/QUARTER LONG HAS BEEN WELDE been cleared of all junk, to the level. have been remediated in action equipment and junication equipment and junication.	DCATION OR D OR  Tash, flow lines and  compliance with k have been removed	
<ul> <li>✓ Rat hole and cellar have been fille</li> <li>✓ A steel marker at least 4" in diam</li> <li>OPERATOR NAME, LEAS UNIT LETTER, SECTION PERMANENTLY STAMP</li> <li>✓ The location has been leveled as nother production equipment.</li> <li>✓ Anchors, dead men, tie downs and If this is a one-well lease or last reoCD rules and the terms of the Operation lease and well location.</li> </ul>	ed and leveled. Cathodic protected and at least 4' above ground at least 4' above been cut off at least 6' a	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION AND AND AND AND AND AND AND AND AND AN	properly abandoned. concrete. It shows the ARTER/QUARTER LONG HAS BEEN WELDE been cleared of all junk, to the level. have been remediated in action equipment and junication equipment and junication.	DCATION OR D OR  Tash, flow lines and  compliance with k have been removed	
<ul> <li>□ Rat hole and cellar have been fill</li> <li>□ A steel marker at least 4" in diam</li> <li>□ OPERATOR NAME, LEAS</li> <li>□ UNIT LETTER, SECTION</li> <li>□ PERMANENTLY STAMP</li> <li>□ The location has been leveled as a other production equipment.</li> <li>□ Anchors, dead men, tie downs and</li> <li>□ If this is a one-well lease or last reduction of the Operation lease and well location.</li> <li>□ All metal bolts and other materials to be removed.)</li> <li>□ All other environmental concerns</li> <li>□ Pipelines and flow lines have been</li> </ul>	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground at least 4' above ground the second at least 4' above ground the second at least 4' above ground at least 4' above ground the second at least 4' above been cut off at least 4' above been removed. Portable by the second at least 4' above been addressed as per OC 5' above 5'	the terms of the Oper tion holes have been purely level has been set in API NUMBER, QUALINFORMATION AND AND AND AND AND AND AND AND AND AN	properly abandoned. concrete. It shows the ARTER/QUARTER LON HAS BEEN WELDE been cleared of all junk, to the local desired in action equipment and junk wed. (Poured onsite concrete co	CATION OR DOR  Tash, flow lines and  compliance with the have been removed ete bases do not have	
<ul> <li>☑ Rat hole and cellar have been fill</li> <li>☑ A steel marker at least 4" in diam</li> <li>☐ OPERATOR NAME, LEAS UNIT LETTER, SECTION PERMANENTLY STAMP</li> <li>☑ The location has been leveled as other production equipment.</li> <li>☑ Anchors, dead men, tie downs an</li> <li>☑ If this is a one-well lease or last reform lease and the terms of the Operation lease and well location.</li> <li>☑ All metal bolts and other materials to be removed.)</li> <li>☑ All other environmental concerns</li> <li>☑ Pipelines and flow lines have bee retrieved flow lines and pipelines.</li> </ul>	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground the second at least 4' above been cut off at least 4' above been cut off at least 5' above been removed. Portable 6' above been addressed as per OC 6' nabandoned in accordance with	the terms of the Oper tion holes have been publication holes have been publication has been set in API NUMBER, QUALINFORMATION ALL INFORMATION ALL two feet below groundery and pit location(s). All flow lines, produces have been removed by the publication of th	properly abandoned. concrete. It shows the ARTER/QUARTER LON HAS BEEN WELDE been cleared of all junk, to all level. have been remediated in action equipment and junk wed. (Poured onsite concrete All fluids have been remediated and the state of the stat	peraction or DOR DOR  Tash, flow lines and  compliance with the have been removed the ete bases do not have the loved from non-	
<ul> <li>☑ Rat hole and cellar have been fill</li> <li>☑ A steel marker at least 4" in diam</li> <li>☐ OPERATOR NAME, LEAS UNIT LETTER, SECTION PERMANENTLY STAMP</li> <li>☑ The location has been leveled as other production equipment.</li> <li>☑ Anchors, dead men, tie downs and ☑ If this is a one-well lease or last re OCD rules and the terms of the Operation lease and well location.</li> <li>☑ All metal bolts and other materials to be removed.)</li> <li>☑ All other environmental concerns ☑ Pipelines and flow lines have been retrieved flow lines and pipelines.</li> <li>☑ If this is a one-well lease or last red</li> </ul>	ed and leveled. Cathodic protect eter and at least 4' above ground eter and at least 4' above ground the second process of the secon	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION ALL INFORMATION ALL TWO feet below groundery and pit location(s). All flow lines, produces have been removed assess have been removed D rules.  19.15.35.10 NMAC.	properly abandoned. concrete. It shows the ARTER/QUARTER LON HAS BEEN WELDE been cleared of all junk, to all level. have been remediated in action equipment and junitived. (Poured onsite concretal lines have been removed the lines have been removed.)	compliance with k have been removed ete bases do not have hoved from non-	
A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP   The location has been leveled as a other production equipment.  Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation lease and well location.  All metal bolts and other materials to be removed.)  All other environmental concerns  Pipelines and flow lines have been retrieved flow lines and pipelines.  If this is a one-well lease or last relocation, except for utility's distribution.	ed and leveled. Cathodic protect eter and at least 4' above ground eter and at least 4' above ground the second process of the secon	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION ALL INFORMATION ALL TWO feet below groundery and pit location(s). All flow lines, produces have been removed assess have been removed D rules.  19.15.35.10 NMAC.	properly abandoned. concrete. It shows the ARTER/QUARTER LON HAS BEEN WELDE been cleared of all junk, to all level. have been remediated in action equipment and junitived. (Poured onsite concretal lines have been removed the lines have been removed.)	compliance with k have been removed ete bases do not have hoved from non-	
A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP   The location has been leveled as a other production equipment.  Anchors, dead men, tie downs and  If this is a one-well lease or last re OCD rules and the terms of the Operate from lease and well location.  All metal bolts and other materials to be removed.)  All other environmental concerns  Pipelines and flow lines have bee retrieved flow lines and pipelines.  If this is a one-well lease or last re location, except for utility's distribution  (Jimmie Cooper)	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground at least emaining well on lease, the batter at least emaining well on lease, the batter at least emaining well on lease, the batter at least emaining well on lease at least emaining well on lease at least emaining well on lease: all elect on infrastructure All of the point at least 4' above ground at least 4' above gro	the terms of the Oper tion holes have been publication holes have been publication has been set in API NUMBER, QUALINFORMATION ALL INFORMATION INFORMATION ALL INFORMATION INFORMATION ALL INFORMATION INFORMA	properly abandoned. concrete. It shows the  ARTER/QUARTER LO ON HAS BEEN WELDE  peen cleared of all junk, to add level. have been remediated in action equipment and junk  wed. (Poured onsite concrete  All fluids have been removed the lines have been removed the left at the landowned	compliance with k have been removed ete bases do not have hoved from non-	
A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP   The location has been leveled as a other production equipment.  Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation lease and well location.  All metal bolts and other materials to be removed.)  All other environmental concerns  Pipelines and flow lines have been retrieved flow lines and pipelines.  If this is a one-well lease or last relocation, except for utility's distribution.	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground at least emaining well on lease, the batter at least emaining well on lease, the batter at least emaining well on lease, the batter at least emaining well on lease at least emaining well on lease at least emaining well on lease: all elect on infrastructure All of the point at least 4' above ground at least 4' above gro	the terms of the Oper tion holes have been publication holes have been publication has been set in API NUMBER, QUALINFORMATION ALL INFORMATION INFORMATION ALL INFORMATION INFORMATION ALL INFORMATION INFORMA	properly abandoned. concrete. It shows the  ARTER/QUARTER LO ON HAS BEEN WELDE  peen cleared of all junk, to add level. have been remediated in action equipment and junk  wed. (Poured onsite concrete  All fluids have been removed the lines have been removed the left at the landowned	compliance with k have been removed ete bases do not have hoved from non-	
A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP   The location has been leveled as a other production equipment.  Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation lease and well location.  All metal bolts and other materials to be removed.)  All other environmental concerns  Pipelines and flow lines have been retrieved flow lines and pipelines.  If this is a one-well lease or last re location, except for utility's distribution (Jimmie Cooper)  When all work has been completed, re	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground at least 4' above been cut off at least 6' at l	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION AND AND AND AND AND AND AND AND AND AN	properly abandoned. concrete. It shows the  ARTER/QUARTER LOON HAS BEEN WELDE  peen cleared of all junk, to add level. have been remediated in action equipment and junk  wed. (Poured onsite concrete  All fluids have been removed the lines have been removed.	compliance with the have been removed ete bases do not have noved from non-lifted from lease and well ers request	
A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP   The location has been leveled as a other production equipment.  Anchors, dead men, tie downs and  If this is a one-well lease or last re OCD rules and the terms of the Operate from lease and well location.  All metal bolts and other materials to be removed.)  All other environmental concerns  Pipelines and flow lines have bee retrieved flow lines and pipelines.  If this is a one-well lease or last re location, except for utility's distribution  (Jimmie Cooper)	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground at least 4' above been cut off at least 6' at l	the terms of the Oper tion holes have been publication holes have been publication has been set in API NUMBER, QUALINFORMATION ALL INFORMATION INFORMATION ALL INFORMATION INFORMATION ALL INFORMATION INFORMA	properly abandoned. concrete. It shows the  ARTER/QUARTER LOON HAS BEEN WELDE  peen cleared of all junk, to add level. have been remediated in action equipment and junk  wed. (Poured onsite concrete  All fluids have been removed the lines have been removed.	compliance with k have been removed ete bases do not have hoved from non-	
A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP   The location has been leveled as other production equipment.  Anchors, dead men, tie downs and  If this is a one-well lease or last re  OCD rules and the terms of the Operat  from lease and well location.  All metal bolts and other materials to be removed.)  All other environmental concerns  Pipelines and flow lines have bee  retrieved flow lines and pipelines.  If this is a one-well lease or last re  location, except for utility's distribution  (Jimmie Cooper)  When all work has been completed, re  SIGNATURE  TYPE OR PRINT NAME _LINDSAME.	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground at least 5' above been cut off at least 6' at le	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION AND AND AND AND AND AND AND AND AND AN	properly abandoned. concrete. It shows the  ARTER/QUARTER LOON HAS BEEN WELDE  peen cleared of all junk, to add level. have been remediated in action equipment and junk  Wed. (Poured onsite concrete  All fluids have been removed  I lines have been removed  The landowned  The	compliance with the have been removed ete bases do not have noved from non-lifted from lease and well ers request	
A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP   The location has been leveled as a other production equipment.  Anchors, dead men, tie downs and If this is a one-well lease or last ro OCD rules and the terms of the Operat from lease and well location.  All metal bolts and other materials to be removed.)  All other environmental concerns Pipelines and flow lines have bee retrieved flow lines and pipelines.  If this is a one-well lease or last rolocation, except for utility's distribution (Jimmie Cooper)  When all work has been completed, resulting the Cooper of	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground at least 5' and 5' an	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION ALL INFORMATION ALL INFORMATI	properly abandoned. concrete. It shows the  ARTER/QUARTER LOON HAS BEEN WELDE  peen cleared of all junk, to add level. have been remediated in action equipment and junk  Wed. (Poured onsite concrete  All fluids have been removed  I lines have been removed  The landowned  The	compliance with have been removed ete bases do not have hoved from non-lifted from lease and well ers request	
A steel marker at least 4" in diam  OPERATOR NAME, LEAS  UNIT LETTER, SECTION  PERMANENTLY STAMP   The location has been leveled as other production equipment.  Anchors, dead men, tie downs and  If this is a one-well lease or last re  OCD rules and the terms of the Operat  from lease and well location.  All metal bolts and other materials to be removed.)  All other environmental concerns  Pipelines and flow lines have bee  retrieved flow lines and pipelines.  If this is a one-well lease or last re  location, except for utility's distribution  (Jimmie Cooper)  When all work has been completed, re  SIGNATURE  TYPE OR PRINT NAME _LINDSAME.	ed and leveled. Cathodic protected and at least 4' above ground eter and at least 4' above ground at least 5' and 5' an	the terms of the Oper tion holes have been put level has been set in API NUMBER, QUALINFORMATION ALL INFORMATION ALL INFORMATI	properly abandoned. concrete. It shows the  ARTER/QUARTER LOON HAS BEEN WELDE  peen cleared of all junk, to add level. have been remediated in action equipment and junk  wed. (Poured onsite concrete  All fluids have been removed the lines have been removed the lines have been removed the landowned  edule an inspection.  NALYSTDATE  mian.com PHONI	compliance with k have been removed ete bases do not have noved from non-diffrom lease and well ers request  12/09/2020 E: _(432)207-3054	



EMNRD - DISTRIC 1 1625 N FRENCH DRIVE HOBBS NM 88240 575-393-6161

## PLUG & ABANDON - SITE OK TO RELEASE

OPERATOR NAME	3001111	LSI KOIAI	ILO		
API	30-025-30125				
PROPERTY NAME					
9					
WELL LOCATION	UL- LOT	SECTION	TOWNSHIP	RANGE	COUNTY
3	N	28	18S	37E	LEA
					в
			LOCATI	ON-OK	
DATE:	: 12-10-2020		UNDE	RGROUN	ID MARKER
P\ A'D OK TO RELASE	YES				
					36 F
APPROVED BY	GARY	ROBINSON		-1.0	
APPROVED BY TITLE:	GARY C/O			-1.	