State Of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham

Governor

Sarah Cottrell Propst

Cabinet Secretary

Todd E. Leahy, JD, PhD

Deputy Cabinet Secretary

Adrienne Sandoval Division Director



Field Inspection Program "Preserving the Integrity of Our Environment"



28-Dec-20

CHEVRON MIDCONTINENT, L.P.

6301 Deauville Blvd Midland, TX 79706

Dear Operator:

LETTER OF VIOLATION - Field Inspection

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-025-31572] LOVINGTON PADDOCK UNIT #142

OGRID: 241333

F-06-17S-37E 2480 FNL 2190 FWL

Inspection Date 12/10/2020

Type Inspection

Inspector

Corrective Action Due By

Inspection No.

Routine Inspection

[EZB] Eugene Bolton

3/31/2021

iEZB2034538893

Violations:

Rule

Violation

Unauthorized Release

19.15.10.8 Safety Procedures for Drilling and Production

Comment:

Remove release topped with gravel. 5 bbl threshold requires form C-141.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Cyr BLE

Eugene Bolton, Compliance Ofc.

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.