

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N French Dr, Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S St. Francis Dr., Santa Fe, NM 87505

NOBIS OGD
AUG 30 2012
RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources
 CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-22004
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator XOG OPERATING, LLC		6. State Oil & Gas Lease No. OG-534
3. Address of Operator P. O. BOX 352 MIDLAND, TX 79702		7. Lease Name or Unit Agreement Name STATE WE K
4. Well Location Unit Letter <u>F</u> : <u>1980</u> feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>WEST</u> line Section <u>15</u> Township <u>21S</u> Range <u>35E</u> NMPM LEA County		8. Well Number <u>1</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number <u>020451</u> <u>236790</u>
10. Pool name or Wildcat OSUDO, MORROW, S. (20451) OSUDO, WOLFCAMP, S. (82280)		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: Request TA Status <input checked="" type="checkbox"/>
---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/23/12 Run MIT. Pressure to 500# for 30 minutes as per NMOCD requirements. Test witnessed by Mark Whitaker of NMOCD. Chart attached. Request continued TA Status.

This Approval of Temporary Abandonment Expires 8-23-2014


Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE PRODUCTION ANALYST DATE 8/27/12
 Type or print name ANGIE CRAWFORD E-mail address: acrawford@xogoperating.com PHONE: 432-683-3171

For State Use Only
 APPROVED BY: [Signature] TITLE DIST. MGR DATE 9-5-2012
 Conditions of Approval (if any):
 SEP 05 2012

PRINTED IN U.S.A.



RECEIVED
24

AUG 30 2012

HOBBS OGD