

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Hobbs

HOBBS OCD

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

RECEIVED

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator OXY USA Inc. 16696	5. Lease Serial No. NM 2379
3a. Address P.O. Box 50250 Midland, TX 79710	3b. Phone No. (include area code) 432-685-5717	6. If Indian, Allottee or Tribe Name
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 610 FNL 660 FEL NENE (A) Sec 26 T22S R32E	8. Well Name and No. Covington A Federal (#19)	9. API Well No. 30 025-31853
	10. Field and Pool, or Exploratory Area Red Tank Delaware, W.	11. County or Parish, State Lea, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Accepted as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.

10/17/12 MIRU PU, NDWH, NUBOP
10/18/12 Rel TAC, POOH w/ tbg, RIH & set CIBP @ 7541'
10/19/12 Standby wait on cement pump
10/22/12 RIH & tag CIBP @ 7541', circ hole w/ 10# MLF, spot 25sx CL C cmt, Calc TOC 7162'. PUH to 6361', spot 25sx CL C cmt, PUH, WOC
10/23/12 RIH & tag cmt @ 5492' Appr by Jim Amos-BLM, POOH. RIH & set CIBP @ 4902', circ hole w/ 10# MLF, spot 35sx CL C cmt, POOH.
10/24/12 RU WL, RIH & tag @ 3897', tag to high, POOH w/ WL. RIH w/ tbg & tag cmt @ 4406', POOH. RIH w/ WL & perf 4-1/2" & 7-5/8" @ 2784', RDWL. RIH & set pkr @ 2389', EIR @ 2BPM w/ returns up 4-1/2" X 7-5/6" & 7-5/8" X 10-3/4", sqz 50sx CL C cmt, SI, WOC.
10/25/12 Rel pkr, RIH & tag cmt @ 2582' POOH. RIH w/ WL & perf 4-1/2" & 7-5/8" @ 1114', POOH. RIH & set pkr @ 340', EIR @ 2BPM w/ full returns up 4-1/2" X 7-5/6" & 7-5/8" X 10-3/4", sqz 160sx CL C cmt, SI, WOC. Rel pkr, RIH & tag cmt @ 678', POOH. RIH w/ WL & perf 4-1/2" & 7-5/8" @ 350', RDWL. ND BOP, NUWH. EIR @ 2BPM w/ full returns up 4-1/2" X 7-5/6" & 7-5/8" X 10-3/4", circ 200sx CL C cmt, circ cmt out 7-5/8" X 10-3/4", close in 10-3/4", continue pumping, lost circ, flush to clear perfs @ 350', SI @ 100#, WOC.
10/26/12 ND WH, RIH & tag cmt @ 319' inside 4-1/2" csg. Contact Jim Amos-BLM, rec appr to perf @ 319' & resqz. ND Lubr, NU WH, pressure test 350# w/ no loss. NDWH, RIH & perf @ 319', circ 75sx CL C cmt to surf. POOH, top off csg, RDPU.

RECLAMATION

DUE 4-24-13

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

David Stewart

Title Regulatory Advisor

Signature

Date

10/22/12

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

DEC 2 2012

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

(Instructions on page 2)

DEC 10 2012