St mit Copies To Appropriate District [ate Qflice Fnergy Minera		Form C-103
District I	Is and Natural Resources	June 19, 2008
	RVATION DIVISION	30-025-40834
District III 1220 Sc	outh St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 JAN 03 2013 Sant District IV	a Fe, NM 87505	STATE FEE 🛛 🦳
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPOR		7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT PROPOSALS.)		North Hobbs G/SA Unit
1. Type of Well: Oil Well X Gas Well Other	/	8. Well Number
Oil Well X Gas Well Other 2. Name of Operator /		9. OGRID Number
Occidental Permian Ltd.		157984
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 4294, Houston, TX 77210-4294 4. Well Location		Hobbs; Grayburg-San Andres
Unit Letter <u>L</u> : 2035 feet from	the South line and	
Section 18 Townshi		NMPM County Lea
	now whether DR, RKB, RT, GR, e	
12. Check Appropriate Box t	3670.3' GR	Report or Other Data
		report, or other Dum
NOTICE OF INTENTION TO:	SUE	SEQUENT REPORT OF:
EMPORARILY ABANDON CHANGE PLANS		
_		
)THER:	1	/2" Production Casing x Rig Down X
 Describe proposed or completed operations. (Clearl of starting any proposed work). SEE RULE 1103. or recompletion. 		
	See Attached	
[}		· · · · · · · · · · · · · · · · · · ·
Spud Date: 12/16/12	Rig Release Date:	12/22/12
hereby certify that the information above is true and co	mplete to the best of my knowleds	ge and belief.
GIGNATURE Mark Stephens	TITLE Regulatory Co	mpliance_Analyst_DATE12/28/12
	Mark Stephens	
Type or print name <u>Mark Stephens</u>	E-mail address:	
Por State Use Only	Petroleum I	Engineer A 9 9640
APPROVED BY	TITLE	Engineer $JAN 0 3 2013$
Conditions of Approval (if any):		
-		JAN Q 8 2013
		JAN V 8 LOIO V

North Hobbs G/SA Unit No. 833 API No. 30-025-40834

12/20/12 - Drill 7-7/8" production hole to 4667'.

12/21/12 -

12/22/12: Rig up casing crew and run 115 jts. 5-1/2", 17#, J-55, LT&C casing with 20 centralizers and set at 4647'. RU Halliburton and cement first stage with 240 sx. Premium Plus. Plug down, drop bomb, open DV tool (@ 3566') x circulate 16 sx. to surface. Cement second stage with 420 sx. Interfill 'C (lead) x 100 sx. Premium Plus (tail). Circulate 0 sx. to surface off second stage. ND BOP stack. NU wellhead x test to 3000# psi. Jet pits x rig down.

Release drilling rig at 6:00 a.m., 12/22/12.