Submit 1 Copy To Appropriate District Office	State of New Mexico	_Form C=103
District I – (575) 393-6161 HOBBS OC	nergy, Minerals and Natural Resources	Revised August 1, 2011
. 1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 880 CT 2 4 201	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	30-025-39047
District III - (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease  STATE  FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV (505) 476-3460	Santa Fe, NM 87505	STATE STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, RECEIVED	,	37268
0/303	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. House Ivanie of One rigidation Ivanie
DIFFERENT RESERVOIR. USE "APPLICATION	N FOR PERMIT" (FORM C-101) FOR SUCH	State Sec 12
PROPOSALS.)   1. Type of Well: Oil Well   Gas V	Well [] Other	8. Well Number
		1
2. Name of Operator Vanguard Per	mian LLC	9. OGRID Number
3. Address of Operator 2626 JBS Parkway Ste 205B Odessa Tx 79761		2583 <b>650</b> 10. Pool name or Wildcat
3. Address of Operator 2020 JBS Pari	tway Ste 203B Odessa 1x 79761	Lovington Paddock
4. Well Location		
Unit Letter E: 1,650 feet from the North line and 330 feet from the East_line		
	Township 17S Range 36E	NMPM Lea County
	Elevation (Show whether DR, RKB, RT, GR, e	
	25' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTEN		JBSEQUENT REPORT OF:
	JG AND ABANDON REMEDIAL WO	times to the second
		DRILLING OPNS. P AND A
PULL OR ALTER CASING MUI DOWNHOLE COMMINGLE	LTIPLE COMPL  CASING/CEME	ENI JOB ET
DOWNANCE COMMININGLE		
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Completed well in Lovington Paddock interval. Details of the work are attached.		
**		
Spud Date:	Rig Release Date:	
handa a san a		and the same of th
I haraby cartify that the information above	is true and complete to the best of my knowle	A = A + A + A + A + A + A + A + A + A +
Thereby certify that the information above	is title and complete to the best of my knowle	eage and benef.
and the state of t	452 )	
SIGNATURE 1	TITLE SR. Operations E	Engineer DATE 10-15-12
Type or print name <u>C.M. Bloodworth, P.E.</u> E-mail address: <u>mbloodworth@vnrllc.com</u> PHONE: 432-362-2209		
	en de la companya de La companya de la co	· · · · · · · · · · · · · · · · · · ·
For State Use Only		
APPROVED BY:	Petroleum Engin	DATE JAN 3 0 2013
Conditions of Approval (Lanv):		
PA Lovington Grayburg - San Andres		
TH LOVINGTON Wray Durg - Jan Andres		

## Feb 16 2012- Feb 25 2012

MIRU. Pickup 4 3/4" bit, 6-3 1/2" DC's on 2 7/8" tbg. Tagged CIBP @ 5737'. Started drilling on CIBP. Jarred and drilled on CIBP. Plug came loose. RIH with tbg dn to 6300'. Could not circulate hole. Lower Paddock perfs taking fluid. MIRU Jarrel Wirline. Set RBP @ 6250'. Jarrel WLU. Perforated upper Paddock with 2 spf from 6138-40', 6156-60', 6168-6172',6182-86', 6206-08', & 6236-38', RD WL. TIH with PPI . Tagged RBP @6250'. MIRU Crain Acid. Drop FCV. Establish rate thru FCV. Spot 30 bbls 20 % NEFE acid to tool. Break down perfs @ 6236-38 with 100#. pump 2 bbls acid @ 2 bpm with 100#. Move to 6206-08 break down at 400# surface #.; pumped 3 bbls acid at 2 bpm 400#. Move to 6168-72'. Break dn @ 360#. Pump 3 bbls acid @ 2bpm 1000#. Move to 6156-60'. Break dn @ 1000# pumped 4 bbls acid @ 800#. Move to 6156-60'. Break dn @ 800#. POH with PPI packer. RIH with packer and set @ 6120'. Started swabbing.

Feb 28-Mar 1 2012 Swab test well.

## Mar 2 2012 - Mar 14 2012

Release packer and POH with pkr and RBP. TIH with cmt ret and set @ 6190'. MIRU Par Five cementers. Mix and pump 250 sxs class H-neat. Max press 1450#. Displaced to ret. Sting out of ret.; Reverse out. POH with tbg. TIH with packer and set @ 6100'. MIRU Crain Acid. Tried to pump into perfs from 6138-6186' with water and could not. Spotted 2 bbls acid to packer. Pumped into perfs @ 1/4 bpm with 3500#. Formation broke with acid.; Pumped 1500 gals 20% NEFE acid dn 2 7/8 tbg @ 2.5 bpm with 2800# ave inj pres. Dropped 1 salt block and got 800# increase. Max press 3600#. SI 1 hr. TP 1300#. Blew well dn. Well flowed 30 bbls water. Swab well. Last oil cut 18% oil swabbing from SN. Release packer and POH. Ran RBP and packer. Set RBP @ 5460' and packer @ 5320'.; Test swab San Andres perfs from 5384-5436'. MIRU Crain Acid and pumped 1000 gals zylene into perfs @5384-5436' @ 1 BPM with 2500#. MIRU Crain Acid. Pumped 1500 gals 15% NEFE acid dn 2 7/8" tbg @ ave 2.5 bpm with ave press 2600#. Made 1 swab run. Fluid level @ 2700' with oil cut on first run 7%. Released packer and POH. Laid dn 2 7/8 ws. MI 2 3/8 production string. MI and set 320 pumping unit. Install electrical generator with panel. MIRU pulling unit and space well out. Wait on tank battery installation.

## Mar 27 2012 - Apr 3 2012

POH with pmp and rods. NUBOP. POH with tbg. RIH with packer to 5080'. Circulate water on backside. Set Packer. Dump 2 saxs sand on RBP. Pumped into San Andres perfs @ 5384-5420' @ 1.5 bbls per min with 800#. MIRU Par Five cementers. Pump into perfs @ 1.5 bpm @ 800#. Mix and pump 150 sxs Class H with 1% calculated. Achieved 3000# squeeze. Released packer and POH. TIH with bit, DC's, and tbg. Tagged cmt @ 5080'. Drilled dn to 5420' and fell out. Pressure tested squeeze to 1000#. Held ok. Circulated sd off RBP. POH with tbg and RBP. RIH with 2 3/8" 4.7 # 8rd EUE production tubing to 6,079'. Upper Paddock perfs 6138-6186'. NU WH. RIH with 2 x 1 1/2" x 16' pmp on 7/8" rods. HWO. Ppg w/generator.

Apr 5 2012 Ppg 4 BOPD, 20 BWPD

June 21 2012 Ppg 4 BOPD, 29 BWPD. SD generator; WO elec line.

Sep 19 2012 Ppg 4 BOPD, 39 BWPD. Elec line installed well on full time.