



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

SUSANA MARTINEZ

Governor

John H. Bemis

Cabinet Secretary

Jami Bailey

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

06-Mar-13

HOBBS OCD

LEGACY RESERVES OPERATING, LP

P. O. BOX 10848

MIDLAND TX 79702

MAR 06 2013

RECEIVED

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

NEWMAN 32 STATE No.001

F-32-23S-38E

30-025-32021-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/05/2013	Routine/Periodic	Mark Whitaker	Yes	No	4/19/2013	iMAW1306445740
Violations						
Absent Well Identification Signs (Rule 103)						

Comments on Inspection: Well sign incorrect (Rule 19.15.16.8). Sign needs be changed to reflect current operator (Legacy not Three Rivers). 1st notice.

NEWMAN 32 STATE No.002

B-32-23S-38E

30-025-37170-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
03/05/2013	Routine/Periodic	Mark Whitaker	Yes	No	4/19/2013	iMAW1306446156
Violations						
Absent Well Identification Signs (Rule 103)						

Comments on Inspection: Well sign incorrect (Rule 19.15.16.8). Sign needs be changed to reflect current operator (Legacy not Three Rivers). 1st notice.

MAR 06 2013

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,



COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER	015H14150977	US POSTAGE
	\$0.46	
	03/06/13	
	Mailed From 88240	

LEGACY RESERVES OPERATING, LP
P.O. BOX 10848
MIDLAND, TX 79702-0848