| Submit I Copy To Appropriate District | State of New Mexico | Form C-103 |
|--|---|--|
| District 1 - (575) 393-6161 | gy, Minerals and Natural Resources | Revised August 1, 2011 WELL API NO. |
| Submit 1 Copy To Appropriate District Office <u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 HOBBS <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 | A CHEERY ATION DUVISION | 30-025-00370 |
| | | 5. Indicate Type of Lease |
| District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 | 1220 South St. Francis Dr. | STATE FEE |
| <u>District IV</u> – (505) 476-3460 | 1220 South St. Francis Dr. JED Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | |
| SUNDRY NOTICES AND | | 7. Lease Name or Unit Agreement Name |
| . (DO NOT USE THIS FORM FOR PROPOSALS TO DRJ DIFFERENT RESERVOIR. USE "APPLICATION FOR | | Lea R State NCAT-A |
| PROPOSALS.) | · · · · · | 8. Well Number |
| 1. Type of Well: Oil Well 🛛 Gas Well | Other | |
| 2. Name of Operator | | 9. OGRID Number |
| Devon Energy Production Company, L.P. | | 6137 10. Pool name or Wildcat |
| 333 W. Sheridan Avenue, Oklahoma City, Oklahoma 73102 (405) 552-7848 | | Anderson Ranch; Cisco-Canyon North |
| 4. Well Location 990 660 | | |
| Unit Letter A 1: 2145 feet from t | | the East line |
| | Township 16S Range 32E | NMPM Lea, County New Mexico |
| | ition (Show whether DR, RKB, RT, GR, etc. | |
| 3,324' | · · · · · · · · · · · · · · · · · · · | |
| | · · · · | |
| 12. Check Appropriat | te Box to Indicate Nature of Notice | , Report or Other Data |
| | | |
| NOTICE OF INTENTIO | | SSEQUENT REPORT OF: |
| | | |
| — | E COMPL CASING/CEMEN | |
| | | |
| | | _ |
| OTHER: | OTHER: Tempo | rary Abandon MIT & Chart |
| 13. Describe proposed or completed operat | tions. (Clearly state all pertinent details, a | nd give pertinent dates, including estimated date |
| | RULE 19.15.7.14 NMAC. For Multiple Co | |
| proposed completion or recompletion. | - | |
| | | |
| | | |
| | · · | |
| 02/11/2013 - 02/19/13 | · . | • • |
| , | two runs w/ 35' of Close H ant DIH & Sat | coord CIPP @ 0750' nor NMOCD shows |
| MIRU. Set CIBP @ 10470. Dump bail cement in | two runs w/ 35' of Class H cmt. RIH & Set IBP @ 9630. Dump bail 35' cmt in two run | second CIBP @ 9750' per NMOCD above s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl | IBP @ 9630. Dump bail 35' cmt in two run | second CIBP @ 9750' per NMOCD above s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl | IBP @ 9630. Dump bail 35' cmt in two run | second CIBP @ 9750' per NMOCD above s. PT csg. to 500psi for 30 min. RDMO PU. 7016 |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl | two runs w/ 35' of Class H cmt. RIH & Set IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires | second CIBP @ 9750' per NMOCD above s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl | IBP @ 9630. Dump bail 35' cmt in two run | second CIBP @ 9750' per NMOCD above s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl ~ This / Aban | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl ~ This / Aban | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl This Aban I hereby certify that the information above is tru | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl ~ This / Aban | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl This Aban I hereby certify that the information above is tru SIGNATURE Type or print name Erin Workman | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires e and complete to the best of my knowled | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl This Aban I hereby certify that the information above is tru SIGNATURE | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires e and complete to the best of my knowled | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl This Aban I hereby certify that the information above is tru SIGNATURE Julia Data Type or print name Erin Workman For State Use Only | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl This A Aban I hereby certify that the information above is tru SIGNATURE Du UMAA Type or print name Erin Workman For State Use Only APPROVED BY: | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires e and complete to the best of my knowled | s. PT csg. to 500psi for 30 min. RDMO PU. |
| MIRU. Set CIBP @ 10470. Dump bail cement in Wolfcamp Perfs. Dump bail 2 runs of cmt. Set Cl This Aban I hereby certify that the information above is tru SIGNATURE Julia Data Type or print name Erin Workman For State Use Only | IBP @ 9630. Dump bail 35' cmt in two run Approval of Temporary donment Expires | s. PT csg. to 500psi for 30 min. RDMO PU. |

MAR 28 2013



