# New Mexico Oil Conservation Division, District 1

1625 N. French Drive

Hobbs, NM 80240 **UNITED STATES** 

	FORM	ΛA	PRO	VE.	D
	OMB	No.	1004	-01	37
¥.		🔿	1	21	20

٠.	Form 3	1160	)-5
	(Marel	20	12)

# DEPARTMENT OF THE INTERIOR

p	
5. Lease Serial No. NM 02218	· · · · · · · · · · · · · · · · · · ·
6. If Indian, Allottee or Trib	e Name


BUREAU OF LAND MANAGEMENT							
SUNDRY N	OTICES AND REPO	ORTS ON V	/ELLS		6. If Indian, Allottee	or Tribe Name	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				N/A			
SUBMI	T IN TRIPLICATE Other	instructions o	n page 2.		7. If Unit of CA/Agr	cement, Name and/or N	0.
1. Type of Well			HOBB	<del>3000</del>	N/A		
Oil Well Gas W		·	MAR 1		8. Well Name and N EL ZORRO E F	o. EDERAL #003	/
2. Name of Operator HALCON HOLE	DINGS, INC		4 5	2013	9. API Well No. 30-041-00170	_	
3a. Address 5100 E. SKELLY DRIVE, SUITE TULSA, OK 74135	650	3b. Phone No. (918) 663-28	(include area coo	de) 'ED	10. Field and Pool o ALLISON; SAN	r Exploratory Area I ANDRES, EAST	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1980 FNL & 660 FEL SEC. 28, T08S, R37E					11. County or Parish, State ROOSEVELT COUNTY, NM		
12. CHEC	K THE APPROPRIATE BO	X(ES) TO IND	ICATE NATURI	E OF NOTIC	CE, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION			TY	PE OF ACT	ION		
✓ Notice of Intent	Acidize	Deep	en .	Produ	uction (Start/Resume)	Water Shut-Off	•
Notice of Intent	Alter Casing	Fract	ure Treat	Recla	mation	Well Integrity	
Subsequent Report	Casing Repair	☐ New	v Construction Reco		mplete	Other	
	Change Plans	<b>✓</b> Plug	and Abandon	Temp	oorarily Abandon	·	
Final Abandonment Notice	Convert to Injection	Plug	Back ·	Wate	r Disposal		
WELL WAS COMPLETED IN THE IS ANDRES. THIS FORMATION HAS POTENTIAL UPHOLE ZONES. PLI AND A CURRENT WELLBORE DIA PERFORMED UNDER BLM BOND  Halcon Holdings Inc. I BLM Operator But Is A Downhole Plugging Of Energy Inc. Approval	NOW BECOME UNECOME  ASE SEE ATTACHED TO  GRAM. THE ESTIMATED  NO. WYB000905; RIDER  S Not The Approva  Approved To Do To  This Well For Ra	NOMIC TO PE HE PROPOSE D STARTING I NO. SUR000: ed he im	ODUCE. A GE ED SUMMARY T DATE TO PERF 3902.	OLOGIC R TO PLUG A TORM THIS	EVIEW INDICATES ND ABANDON, PR WORK IS APRIL 1	S THERE ARE NO OT OPOSED WELLBORI 5, 2013. ALL WORK	HER E DIAGRAM
Is Contigent On Halco			ENDING	ā <u>J</u>	UN 1 2 2013		
14. I hereby certify that the foregoing is tr	•	d/Typed) ••••••••••••••••••••••••••••••••••••					
STEPHEN MILI	NICHIK		Title SR. OPE	RATIONS	ENGINEER		<del></del>
Signature	duir !!	<i></i>	Date 02/21/20	13			
70	THIS SPACE	FOR FEDE	RAL OR STA	ATE OFF	ICE USE		
Approved by /S/ DAVII	D R. GLAS	S	PETR	OLEUM I	ENGINEER	MAR 12.2	013
Conditions of approval, if any, are attached that the applicant holds legal or equitable tientitle the applicant to conduct operations to	tle to those rights in the subjec				ROSWELLF	ELD OFFICE	

Title 18 U.S.C. Section 1001 and Title 18 U.S.C. Section 1012 make Countries any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudylentstatements or preparations and united states any false, first united states and false and

APR 1 1 2013

## El Zorro E Federal #3 P&A Summary

- 1. Contact local BLM representative at least 24 hours before starting operations
- 2. MIRU plugging company rig.
- 3. MIRU Wireline Service. RIH w/ 5½" gauge ring and junk basket to top of perforations @ 4798'KB. POOH. PU & RIH w/ 5½" CIBP to 4780'KB. Set CIBP. PU & TIH w/glass bottom dump bailer w/ 5 sx Class H cement to top of plug. Spot cement on plug (Plug #1: 4780'KB).
- 4. PU & TIH w/ 2 3/8" workstring to top of cement @ 4739'KB. Spot bbls 9.0 ppg drilling mud from 4200'-4739'KB in 5 1/2" casing.
- 5. RIH w/ string shot and perforate casing at 4256'KB w/ 2 shots.
- 6. PU & RIH w/ 5 1/2" cement retainer to 4200'KB. Set retainer.
- 7. Mix and pump 50 sx Class "H" cement into holes (Plug #2: 4156'-4256'KB). Displace cement slurry w/15 bbls fresh water (45 sx below retainer).
- 8. Leave 5 sx cement on top of retainer.
- 9. Pull uphole to 4100'KB. Spot 13 bbls 9.0 ppg (40 cp viscosity) drilling mud on cement and retainer w/13 bbls fresh water. TOOH with tubing and stinger.
- 10. Latch on to 5 1/2" casing. TIH w/string charge on wireline to approximately 3500' KB. Backoff casing.
- 11. Establish circulation via 5 1/2" casing with 9.0 ppg drilling mud. Pull & LD recovered 5 1/2" casing.
- 12. TIH w/ open-ended 2 %" tubing to 3550'KB (50' inside cutoff casing).
- 13. MIRU Cementing Services (NMC Certified Cementer). MI transport loaded with 300 bbls fresh water.
- 14. Mix and pump 33 sx Class "H" cement (16.4 ppg, 1.06 ft³/sk) via tubing at no more than 3 BPM. Flush cement with 13 bbls drilling mud (Plug #3:3450'-3550'KB).
- 15. WOC 12 hrs. RIH w/ tubing and tag cement top ~ 3450'KB.
- 16. MIRU Wireline. RIH w/ string shot and perforate 8 %" casing at 400'KB w/ 2 shots.
- 17. Mix and pump 50 sx Class "H" cement via 8 5%" casing into holes (Plug #4:300'-400'KB). Stage squeeze cement to standing pressure of 500 psi. Displace cement slurry w/18 bbls drilling mud.
- 18. RIH w/ tubing and tag cement top ~ 300'KB.
- 19. Spot final 16 sx Class "H" cement plug from 3'-50'KB (Plug #5). RD cementers.
- 20. Cutoff casing(s) 3' below ground level.
- 21. Weld on ID plate with API number and date plugged (vent ID plate).



Engineer: <u>Stephen Milinichik</u>

Office#: (918) 632-0608


Celi#: (918) 714-1806

Prepared By: SJM

Date: 2/26/2013

Updated: 2-26-2013 SJM

Current



Engineer: <u>Stephen Milinichik</u>
Office#: (918) 632-0608
Cel#: (918) 714-1806

Prepared By: SJM Date: 2/26/2013 Updated: 2-26-2013 SJM

### BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

#### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90<sup>th</sup> day provide the BLM Roswell Field Office (RFO), prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification</u>: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. Monument: Upon abandonment of the well, all casing shall be cut-off at the base of the cellar or 3-feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. Timing Limitation Lease Stipulation / Condition of Approval For Lesser Prairie-Chicken: Oil and gas activities including 3-D geophysical exploration, and drilling will not be allowed in lesser prairie-chicken habitat during the period from March 1 through June 15 annually. During that period, other activities that produce noise or involve human activity, such as the maintenance of oil and gas facilities, geophysical exploration other than 3-D seismic operations, and pipeline, road, and well pad construction, will be allowed except between 3:00 am and 9:00 am. The 3:00 am to 9:00 am restriction will not apply to normal, around-the-clock operations, such as venting, flaring, or pumping, which do not require a human presence during this period. Additionally, no new drilling will be allowed within up to 200 meters of leks known at the time of permitting. Normal vehicle use on existing roads will not be restricted. Exhaust noise from pump jack engines must be muffled or otherwise controlled so as not to exceed 75 db measured at 30 feet from the source of the noise.
- 8. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.