Submit I Copy To Appropriate District <b>HOBBS OCD</b> State of New Mexico Office	Form C-103
District I = (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240DEC 07 2012 District II – (575) 748-1283	30-025-31023
811 S. First St., Artesia, NM 88210  District III - (505) 334-6178  OIL CONSERVATION DIVISION  1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 RECEIVED	STATE X FEE
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	WEST PEARL QUEEN UNIT
1. Type of Well: Oil Well X Gas Well  Other	8. Well Number #205
Name of Operator     STATE OF NEW MEXICO formerly Xeric Oil & Gas Corp	9. OGRID Number 25482
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240	10. Pool name or Wildcat PEARL QUEEN
4. Well Location	
Unit Letter_C:1310feet from the _N line and2630_	feet from theWline
Section 33 Township 19S Range 35E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
12. Check Appropriate Box to Indicate Nature of Notice, R	eport or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON X REMEDIAL WOR	
TEMPORARILY ABANDON	<del></del>
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMEN	T JOB
DOWNHOLE COMMINGLE	
OTHER: OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	d give pertinent dates, including estimated
date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
SEE ATTACHED P&A PROCEDURE	
. [	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge	11 12 6
Thereby certify that the information above is true and complete to the best of my knowledge	e and bener.
$\mathcal{N}_{+}$	
SIGNATURE Wach white COMPLIANCE OFFICER	DATE12/07/2012
The state of the s	
Type or print name _MARK WHITAKER E-mail address: Marka.Whitaker@state.nm. For State Use Only	<u>us</u> PHONE: _575-393-6161
101 pane Obe Only	
APPROVED	
BY:TITLE_	DATE
Conditions of Approval (if any):	

State of New Mexico formerly Xeric Oil & Gas Corp West Pearl Queen Unit No. 205

Set CIBP at 4650' and cap w/ 25 sx cmt. Pressure test csg. Circulate hole w/ 9.5 ppg brine w/ 25 sx salt gel per 100 bbls. Spot 25 sx cmt at 3400'. Spot 25 sx cmt at 1800'. Spot cmt from 455' to surface. Cut off wellhead and install dry hole marker.

\*LUGGING & ABANDONMENT WORKSHEET (2 STRING CSNG) OPERATOR ST. of NM formerly XERICOIL : Gas LEASENAME WEST PEARL QUEEN UNIT WELL # 205 195 RNG 35E 33 TWN SECT 1316 (N/SL FROM 2630 EM)L FORMATION @ TD Queen TD: 5100' PBTD: FORMATION @ PBTD 50ZZ' SIZE SET @ TOC TOO DETERMINED BY 85/8 SURFACE 85/8 405' CIRL. INTMED 1 TOC CITL INTMED 2 51/2 5095 15.5917 PROD CITC. SIZE TOP TOC DETERMINED BY BOT LINER 1 LINER 2 CUT & PULL @ TOP - BOTTOM INTMED 1 4713'-4968' PERFS INTMED 2 OPERATOR PROD \*REQUIRED PLUGS DISTRICT I PLUG RUSTLER (ANEIYD) TYPE SYCKS DEPTH PLUG CMNT YATES TOC Circ **QUEEK** EXALPLES ORAYBURA n cun OH232 2E 6400 20071 SHOE 50 SXS 5350-5450 LAH AHOFE T. SALT 1800 ruur s CIBP/35' 4300 CANTAK REEF nun CIBP 25 SKS 4800" 3400 B. SALT 50 SXS PICUS STUB 3600'-3700' ruu 15 REINR SQZ 200 SXS 400 DELAWARE EWS & C SURF 10505 0-10' BELL CHRYCH n coun CHEMICKNOCK nunii BATTELL CONTOK ELUUM S EH1252 33408 RUOI4 HLDG#5 OCORDETA rwie BLINEBAY TIENT EUU nuore DEDUCARD ruu i i NUUM PLUU # K\*C nwi LEKK K#AXTE ATOKA WOLLOW TD 5100' MIIII DEVOKEUK