Submit I Copy T	o Appropriate District	State of New Mexico			Form C-103			
District I - (575)	istrict I – (575) 393-6161 Energy, Minerals and Natural Resources				August 1, 2011 WELL API NO.			
	25 N. French Dr., Hobbs, NM 88240 strict II - (575) 748-1283				30-025-12578			
811 S. First St., A		NSERVATION DIVISION		5. Indicate Type of Lease				
1000 Dis Danson D.J. Asses NRA 97410			uth St. Francis Dr.		STATE	FEE	$\boxtimes$	
District IV - (50)	ict IV – (505) 476-3460 S. St. Francis Dr., Santa Fe, NM				6. State Oil & C	ias Lease No.		
87505	is Dr., Santa Pe, NM							
(DO MOR HOUSE	SUNDRY NOTION	7. Lease Name or Unit Agreement Name						
	THIS FORM FOR PROPOS SERVOIR. USE "APPLIC	East Pearl Queen Unit						
PROPOSALS.)		8. Well Number 27						
2. Name of C	ell: Oil Well 🔯	9. OGRID Number						
	Mexico formerly Xe	25482						
3. Address o	f Operator	10. Pool name or Wildcat						
	ch Drive, Hobbs, NM	Pearl Queen						
4. Well Loca							}	
		1980 feet from the				rom the <u>E</u>	line	
Sect	on 27	Township 19-S	Range		MPM	County Lea		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)								
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data								
	,	• • •			•			
					SEQUENT REPORT OF: K □ ALTERING CASING□ ILLING OPNS. □ P AND A □			
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WOR TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRI								
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT						I AND A	4	
	COMMINGLE		_					
OTUED.			_	OTHER.				
OTHER:	ihe proposed or compl	eted operations (Clearly s		OTHER:	l give pertinent da	ites including	estimated date	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								
propo	sed completion or reco	ompletion.		-	•	J		
		equipment. POH w/ rods						
		I w/ gauge ring to 4650'. I sing. Held. Spotted 25 sx						
		/13 Tagged plug @ 3770'						
Spott	ed 30 sx cement @ 33	300'. POH w/ tbg. Set pac	ker @ 10'	'. Sqz'd cement in	ito perfs and held	d 500 psi. WO	C. Tagged	
		1800'. Spotted 30 sx @						
		1780'. Spotted 10 sx ceme den fluid and Sqz'd 110 s:						
	ce. Rigged down mo		x centent a	and circulated to	surface WOC.	vermen ceme	int to	
03/07	/13 Moved in welder	and backhoe. Dug out ce	llar. cut o	off wellhead. Wel	ded on Above Gi	ound Dry Ho	le Marker.	
Backfilled cellar. removed deadmen. Cleaned location and moved off.								
Spud Date:	02/27/13	Rig R	elease Dat	te:	03/07/13	ļ		
ļ								
hereby certify	that the information a	above is true and complete	to the best	of my knowledge	and belief			
	10			or my idio wiodge	una conor.			
	MK		_					
SIGNATURE_	-/'W_	TITLE	<u>.                                    </u>			ATE		
Type or print n	ame	E-mail	address:		. Р	HONE:		
For State Use			_			<b></b> .		
PROVED E	v. // 650	- V	$\mathcal{D}$	ist m	12 -	1 7 /	1. 2013	
	Approval (if any)	TILE		2/ // //	DD	A1E <u>~~//</u>		
01 /								
	/ (	/		Form provided by	Forms On-A-Disk · (2	214) 340-9429 · Fo	rmsOnADisk.com	

Jerra