

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

HOBBS OGD
OCT 31 2012

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-39746
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-9713
7. Lease Name or Unit Agreement Name PEDRO 11 STATE
8. Well Number 1
9. OGRID Number 231429
10. Pool name or Wildcat MESCALERO UPPER PENN NORTH

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

MANZANO, LLC

3. Address of Operator

P.O.BOX 2107, ROSWELL, NM 88202-2107

4. Well Location

Unit Letter F : 2025 feet from the NORTH line and 1985 feet from the WEST line

Section 11 Township 10S Range 32E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4269' GL

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE TO:

ABANDON ☐

PULL
DOWNHOLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed work (or state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULES OF THE BOARD OF LAND AND MINES, 5.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/20/12 RIH w/CCL and CIBP. set CIBP @ 3936'
9/25/12 MIRU Scientific Drilling. RIH w/wireline and orient whipstock @ 39.27 degrees. Set whipstock on CIBP @ 3936' w/4k. Start milling on casing. Milled for 15min before cut hole in the casing
9/26/12 Drilled 125' of new formation. RIH w/ Packer Plus Port system (details below), and 5 1/2" hanger to 3916'. Set Perma Plus packer at 3916', open hole packer at 4018', 2nd open hole packer at 4059' and pump out sub at 4060'.
10/9/12 MIRU Baker Hughes Acidizing. Pumped 2,000gl of 15% NEFE acid at a rate of 2BPM & at average treating pressure of 1722psi.
10/10/12-10/19/12 Swab test with 1-5% oil cut and 30-50 BWPD. Rig down pulling unit and get plugging orders.

Spud Date:

5-20-80

Rig Release Date:

6-24-80

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Paul Ragsdale

TITLE OTHER

DATE 10-29-2012

Type or print name PAUL RAGSDALE E-mail address: paul@manzanoenergy.com PHONE: 575-626-7903

For State Use Only

El Gringo

Dist. MGR

MAY 20 2013 5-14-2013