Hydrogen Sulfide Drilling Operations Plan East Lusk 15 Federal Com No. 3H Cimarex Energy Co. of Colorado Unit H, Section 15 T19S-R32E, Lea County, NM

30-025-41179

HOEBS OCD

APR 3 0 2013

- 1 All Company and Contract personnel admitted on location must be trained by a qualifie **CEIVED** H₂S safety instructor to the following:
 - A. Characteristics of H₂S
 - B. Physical effects and hazards
 - C. Proper use of safety equipment and life support systems.
 - D. Principle and operation of H₂S detectors, warning system and briefing areas.
 - E. Evacuation procedure, routes and first aid.
 - F. Proper use of 30 minute pressure demand air pack.
- 2 H₂S Detection and Alarm Systems:
 - A. H₂S detectors and audio alarm system to be located at bell nipple, end of flow line (mud pit) and on derrick floor or doghouse.
- 3 Windsock and/or wind streamers:
 - A. Windsock at mudpit area should be high enough to be visible.
 - B. Windsock at briefing area should be high enough to be visible.
- 4 Condition Flags and Signs:
 - A. Warning sign on access road to location.
 - B. Flags to be displayed on sign at entrance to location. Green flag indicates normal safe condition. Yellow flag indicates potential pressure and danger. Red flag indicates danger (H₂S present in dangerous concentration). Only emergency personnel admitted to location.
- 5 Well control equipment:
 - A. See exhibit "E"

6 <u>Communication:</u>

- A. While working under masks chalkboards will be used for communication.
- B. Hand signals will be used where chalk board is inappropriate.
- C. Two way radio will be used to communicate off location in case of emergency help is required. In most cases cellular telephones will be available at most drilling foreman's trailer or living quarters.
- 7 Drillstem Testing:

No DSTs or cores are planned at this time.

- 8 Drilling contractor supervisor will be required to be familiar with the effects H₂S has on tubular goods and other mechanical equipment.
- 9 If H₂S is encountered, mud system will be altered if necessary to maintain control of formation. A mud gas seperator will be brought into service along with H₂S scavengers if necessary.

Page 3A

MAY 20 2013

H₂S Contingency Plan **East Lusk 15 Federal Com No. 3H** Cimarex Energy Co. of Colorado Unit H, Section 15 T19S-R32E, Lea County, NM

Emergency Procedures

In the event of a release of gas containing H_2S , the first responder(s) must:

- ★ Isolate the area and prevent entry by other persons into the 100 ppm ROE.
- ★ Evacuate any public places encompassed by the 100 ppm ROE.
- \star Be equipped with H₂S monitors and air packs in order to control the release.
- ★ Use the "buddy system" to ensure no injuries occur during the response.
- ★ Take precautions to avoid personal injury during this operation.
- * Contact operator and/or local officials to aid in operation. See list of phone numbers attached.
- ★ Have received training in the:
 - Detection of H₂S, and
 - Measures for protection against the gas,
 - Equipment used for protection and emergency response.

Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO_2). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally, the NM State Police may become involved. NM State Police shall be the Incident Command on scene of any major release. Take care to protect downwind whenever there is an ignition of the gas.

Common	Chemical	Specific	Threshold	Hazardous	Lethal			
Name	Formula	Gravity	Limit	Limit	Concentration			
Hydrogen Sulfide	H₂S	1.189 Air=1	10 ppm	100 ppm/hr	600 ppm			
Sulfur Dioxide	SO ₂	2.21 Air=1	2 ppm	N/A	1000 ppm			

Characteristics of H₂S and SO₂

Contacting Authorities

Cimarex Energy Co. of Colorado's personnel must liaise with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as type and volume of release, wind direction, location of release, etc. Be prepared with all information available including directions to site. The following call list of essential and potential responders has been prepared for use during a release. Cimarex Energy Co. of Colorado's response must be in coordination with the State of New Mexico's "Hazardous Materials Emergency Response Plan" (HMER).

H₂S Contingency Plan Emergency Contacts East Lusk 15 Federal Com No. 3H Cimarex Energy Co. of Colorado Unit H, Section 15 T19S-R32E, Lea County, NM

58

Cimarex Energy Co. of Color	800-969-4789			
Co. Office and After-Hours N				
Key Personnel	T :41-	Office		Mobile
Name	Title	432-620-1934		580-243-8285
Larry Seigrist Scott Lucas	Drilling Manager	452-020-1954		432-894-5572
Roy Shirley	Field Drilling Super			432-634-2136
	Field Superintendent			432-034-2130
ncca o enco el ciclo e posto o enco o enco o enco acten o ciclo o ciclo e posto o enco o enco o enco Artesia	9 2111 1 222 1 223 8 233 9 233 9 233 9 233 9 233 9 233 9 233 9 233 9 233 9 233 9 233 9 2	ennen 14 penne 16 ennen 40 kuller 16 kuller 16 buller 16 Rector at curve 18 kuller 16 kuller 18 kuller 18		 M access of protect to stands in activity Of access of protect of access w protect
Ambulance		911		·····
State Police		575-746-2703		
		575-746-2703		
Sheriff's Office	575-746-9888			
Fire Department	575-746-2701			
Local Emergency Planning	575-746-2122			
New Mexico Oil Conserva	575-748-1283			
Carlsbad				
Ambulance		911		
State Police	575-885-3137			
City Police	·	575-885-2111		
Sheriff's Office	575-887-7551			
Fire Department	575-887-6544			
Local Emergency Planning US Bureau of Land Manag	575-887-6544 575-887-6544			
OS DUI Edu OF Land Manag		575-887-0344		- <u>-</u>
<u>Santa Fe</u>				
New Mexico Emergency R	505-476-9600			
New Mexico Emergency R	505-827-9126			
New Mexico State Emerge	505-476-9635			
National				
National Emergency Resp	800-424-8802			
Medical				
Flight for Life - 4000 24th	806-743-9911			
Aerocare - R3, Box 49F; Lu	806-747-8923			
Med Flight Air Amb - 2301	505-842-4433			
SB Air Med Service - 2505	505-842-4949			
<u>Other</u>				
Boots & Coots IWC		800-256-9688	or	281-931-8884
Cudd Pressure Control	432-699-0139	or	432-563-3356	
Halliburton		575-746-2757		
B.J. Services		575-746-3569		

