Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5	Lease Serial No.
J.	Dease Serial 140.
	NIMNIMATTORAD

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use the abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRI	7. If Unit or CA/Agree	ement, Name and/or No.					
1. Type of Well Oil Well Gas Well Oth	JAY-1	6 20.5	8. Well Name and No. MADERA 35 FED	ERAL 1H			
Name of Operator OXY USA INC.	Contact: DAVIC E-Mail: david_stewart@ox	xy.com RECE		9. API Well No. 30-025-41083			
3a. Address P.O. BOX 50250 MIDLAND, TX 79710	Ph:	hone No. (include area code) 432-685-5717 I32-685-5742	į	10. Field and Pool, or Exploratory JABALINA DELAWARE, SW			
4. Location of Well (Footage, Sec., T		11. County or Parish, and State					
Sec 35 T26S R34E NWNW 46 32.005925 N Lat, 103.447729		LEA COUNTY, NM					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION TYPE OF ACTION							
■ Notice of Intent		□ Deepen	□ Production	on (Start/Resume)	■ Water Shut-Off		
☐ Subsequent Report		☐ Fracture Treat	☐ Reclama		■ Well Integrity		
		☐ New Construction	☐ Recompl		Other Drilling Operations		
☐ Final Abandonment Notice	-	☐ Plug and Abandon	-	rily Abandon	Dining Operations		
13. Describe Proposed or Completed Ope		☐ Plug Back	☐ Water Di	·			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) OXY USA Inc. respectfully requests to amend the approved drilling permit with the following proposed changes. Amend the proposed pilothole from 11150'V to 12800'V. Drilling the pilot hole to 12800'V will SEE ATTACHED FOR (12650') formation by about 150'. Over-pressure is not anticipated at this depth. We are not interested in drilling deep into the Wolfcamp but need enough rat hole to get a log across the bull to the Wolfcamp but need enough rat hole to get a log across the CONDITIONS OF APPROVAL of the 3rd Bone Spring sand. The logging job will be the same as originally permitted. Primary target will remain the Brushy Canyon Delaware. See below for the proposed pilothole cementing plug back procedures. Plug #1 cement w/ 520sx PPC cmt w/ .3% CFR-3(Dispersant) + .3% HR-601(Retarder), 14.4ppg 1.22 yield							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #205464 verified by the BLM Well Information System For OXY USA INC., sent to the Hobbs Committed to AFMSS for processing by KURT SIMMONS on 04/30/2013 ()							
Name(Printed/Typed) DAVID ST	Title SR. REC	Title SR. REGULATORY ADVISOR					
Signature (Electronic S		013					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the subject ct operations thereon.	lease Office	LA	MAY 17	0 2013		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	e to any department of a BUREAU OF LAND	MANAGEMENT					

Additional data for EC transaction #205464 that would not fit on the form

32. Additional remarks, continued

465# 24hr CS (500#-24.5hrs) 50% excess from 12800-11800'.

Plug #2 cement w/ 520sx PPC cmt w/ .3% CFR-3 + .15% HR-601, 14.4ppg 1.22 yield 465# 24hr CS (500#-24.5hrs) 50% excess from 11800-10800'. Plug #3 cement w/ 520sx PPC cmt w/ .3% CFR-3 + .15% HR-601, 14.4ppg 1.22 yield 465# 24hr CS (500#-24.5hrs) 50% excess from 10800-9800'.

Plug #4 cement w/ 520sx PPC cmt w/ .3% CFR-3 + .15% HR-601, 14.4ppg 1.22 yield 465# 24hr CS (500#-24.5hrs) 50% excess from 9800-8800'.

Plug #5 cement w/ 400sx PPC cmt w/ .4% CFR-3 + .2% HR-800(Retarder), 17.5ppg .95 yield 4900# 24hr CS 50% excess from 8800-8200'.

OXY is using the Cameron's 5K Multibowl System, copy attached, the lockdown pins on this system do not need to be removed from the wellhead in order to install the pack-off. The intermediate casing will be tested to 70% of its burst rating, and that, as previously discussed/approved (Madera 17 Fed #1H), this is sufficient test of the pins.

Madera 35 Federal 1H 30-025-41083 OXY USA Inc. May 10, 2013 Conditions of Approval

The original COAs still stand with the following changes:

- 1. Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 5000 (5M) psi.
 - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
 - b. Operator shall perform the intermediate casing test to 70% of the casing burst. This will test the multi-bowl seals.
 - c. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.

JAM 051013