## State of New Mexico

HOBBS Energy, Minerals and Natural Resources Department

Form C-103 Revised 5427-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT 1 1625 N. French Dr. , Hobbs, NM 88240 MAY <b>2 0</b> 2013 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO: 30-025-28332
<u>DISTRICT II</u>	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210 RECEIVED	STATE FEE X
DISTRICT III 1000 Río Brazos Rd, Aziec, NM 87410	6. State Oil & Gas Lease Nò.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	South Hobs (G/SA) Unit
1. Type of Well: Oil Well Gas Well Other Injector	8. Well No. 128
2 Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 - Denver City, TX 79323 4. Well Location	
	et From The West Line
Section 3 Township 19-S Range 38-	E NMPM Lea County
3629' KB	
Pit-or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction M	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or NOTICE OF INTENTION TO: SUB	Other Data SEQUENT REPORT OF:
	OEQUEITI ILLI OITI OIT,
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING  PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME	ALTERING CASING  PLUG & ABANDONMENT  NT JOB  grity Test  x, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME  OTHER: Casing Inter  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date	ALTERING CASING  PLUG & ABANDONMENT  Ority Test  S, including estimated date of starting any
PERFORM REMEDIAL WORK  TEMPORÁRILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OF CASING TEST AND CEME OTHER:  OTHER:  OTHER:  Casing Inter  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	ALTERING CASING  PLUG & ABANDONMENT  NT JOB  grity Test  x, including estimated date of starting any
PERFORM REMEDIAL WORK  TEMPORÂRILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OF CASING TEST AND CEME OTHER:  OTHER:  OTHER:  Casing Inter  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  Date of Test: 04/05/2013	ALTERING CASING  PLUG & ABANDONMENT  Ority Test  S, including estimated date of starting any
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OF CASING TEST AND CEME OTHER:  OTHER:  OTHER:  Casing Inter  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEIE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  Date of Test: 04/05/2013  Pressure Readings: Initial – 560 PSI; 15 min – 560 PSI; 30 min – 560 PSI	ALTERING CASING  PLUG & ABANDONMENT  NT JOB  grity Test  x, including estimated date of starting any
PERFORM REMEDIAL WORK  TEMPORÂRILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OF CASING TEST AND CEME OTHER:  OTHER:  Casing Inter  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE  RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  Date of Test: 04/05/2013  Pressure Readings: Initial – 560 PSI; 15 min – 560 PSI; 30 min – 560 PSI  Length of test: 30 minutes	ALTERING CASING  PLUG & ABANDONMENT  Ority Test  S, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing Interpretations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of Test: 04/05/2013  Pressure Readings: Initial – 560 PSI; 15 min – 560 PSI; 30 min – 560 PSI  Length of test: 30 minutes  Witnessed: NO	ALTERING CASING PLUG & ABANDONMENT NT JOB grity Test S, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER: Casing Inter  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  Date of Test: 04/05/2013  Pressure Readings: Initial – 560 PSI; 15 min – 560 PSI; 30 min – 560 PSI Length of test: 30 minutes  Witnessed: NO  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed of closed according to NMOCD guidelines agency. A general-permit of an (attached) alternative or an (attached) alternative.	ALTERING CASING PLUG & ABANDONMENT NT JOB  grity Test  s, including estimated date of starting any completion or recompletion.  That any pit or below-grade torik has been/will be
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OF COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of Test: 04/05/2013  Pressure Readings: Initial – 560 PSI; 15 min – 560 PSI; 30 min – 560 PSI  Length of test: 30 minutes  Witnessed: NO  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	ALTERING CASING PLUG & ABANDONMENT NT JOB  grity Test  s, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be The OCD-approved
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Casing Inter  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  Date of Test: 04/05/2013  Pressure Readings: Initial – 560 PSI; 15 min – 560 PSI; 30 min – 560 PSI Length of test: 30 minutes  Witnessed: NO  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines a general-permit or an (attached) alternation plan	ALTERING CASING PLUG & ABANDONMENT NT JOB  grity Test S, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be be OCD-approved C Associate  DATE 05/15/2013
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OF COMMENCE DRILLING OF COMMENCE DRILLING OF COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing Interproposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Date of Test: 04/05/2013  Pressure Readings: Initial – 560 PSI; 15 min – 560 PSI; 30 min – 560 PSI  Length of test: 30 minutes  Witnessed: NO  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines a general permit or an (attached) alternational plan.  SIGNATURE Administrative.	ALTERING CASING PLUG & ABANDONMENT NT JOB  grity Test  s, including estimated date of starting any completion or recompletion.  That any pit or below-grade took has been/will be The OCD-approved  C Associate  DATE 05/15/2013  TELEPHONE NO. 806-592-6280
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER: Casing Inter  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  Date of Test: 04/05/2013  Pressure Readings: Initial – 560 PSI; 15 min – 560 PSI; 30 min – 560 PSI  Length of test: 30 minutes  Witnessed: NO  Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines a general permit or an (attached) alternative plan  SIGNATURE TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy_johnson@oxy.com	ALTERING CASING PLUG & ABANDONMENT NT JOB  grity Test S, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be be OCD-approved C Associate  DATE 05/15/2013

MAY 2.9 2013

