### SULTANDA SUL

# In Reply Refer to 3162.4 (P0220)

# United States Department of the Interior

## **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene Carlsbad, New Mexico 88220-6292 www.nm.blm.gov



JUN 03 2013

**RECEIVED** 

May 30, 2013

CIMAREX ENERGY CO. 600 N. MARIENFELD ST. STE: 600 MIDLAND, TX 79701

30.025-40085

## Gentlemen:

Your Application for Permit to Drill (APD) for the well listed below has expired because drilling has not commenced per Onshore Order #1:

**LEASE** 

WELL NAME AND LOCATION

**EXPIRATION** 

NMNM052

MALLON 35 FEDERAL -6

03/09/2013

2310' FNL & 330 FWL, SWNW, sec. 35, T. 19 S., R. 34 E.

If the well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this wells at a later date, please submit a complete application (1 original and 3 copies) to this office. Since the original APD has expired, the resubmitted APD will be subject to all processing requirements including the \$6,500 application fee and the 30-day posting period. Please note on the resubmitted APD that it was previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Johnny Dickerson at (575) 234-5914.

Sincerely,

George MacDonell

Acting Assistant Field Manager, Lands & Minerals

cc: NMOCD