Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office District I HOBBST Minerals and Natural Resources	June 19, 2008
A CARACA AND A CAR	WELL API NO. 30-025-20283
1301 W. Grand Ave., Artesia, NM 882101N 0 6 2010220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd; Aztec, NM 87410 Santa Fe, NM 87505	STATE X FEE
District_IV 1220 S. St. Francis Dr., Santa Fe, NM RECEIVED 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: NEW MEXICO S STATE
1. Type of Well: Oil Well ☑ Gas Well ☐ Other	8. Well Number 25
2. Name of Operator	9. OGRID Number
XTO Energy, Inc. 3. Address of Operator	005380 10. Pool name or Wildcat
200 N. Loraine, Ste. 800 Midland, TX 79701	BLINEBRY
4. Well Location	
Unit Letter N : 810 feet from the SOUTH line and	2130 feet from the WEST line
Section 2 Township 22S Range 37E	NMPM County IEA
11. Elevation (Show whether DR, RKB, RT, GR, et	c.)
12. Check Appropriate Box to Indicate Nature of Notice, l	Report, or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRILLI	NG OPNS. P AND A 🗸 🗵
PULL OR ALTER CASING	ОВ
DOWNHOLE COMMINGLE LI Liabili	wed for plugging of well bore only. ity under bond is retained pending receipt 03 (Subsequent Report of Well Plugging)
which	may be found at OCD Web Page under www.cmnrd.state.nm.us/ocd.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.	ve pertinent dates, including estimated date
05/29/2013: MIRU PU. RIH String #1, tag @ 5545'. RIH String #2, tag @ 05/31/2013: String #2 - Spot 50sx cmt @ 5551', PUH & spot 50sx cmt @ Move to String #3. Pump 9bbls cmt to surf. Sting #2 & 3 cmt to surf. 06/03/2013: String #1 - Spot 50sx class 'C' cmt @ 5570', per M. Whita 06/04/2013: Tag TOC @ 3798'. Press TCA to 1000psi w/no loss. Okay to 'C' cmt @ 3796'. WOC. Tag TOC @ 1750'. Perf 4 shots @ 1420. Pump 60sx 06/05/2013: Tag TOC @ 1080'. Perf 4 shots @ 360'. EIR. Pump 250sx 'C'	3520'. Circ 40sx class 'C' to surf. ker (OCD). proceed per M. Whitaker. Spot 55sx class C out 9-5/8". WCC.
csg @ surf. RD PxA. Cut off WH & Anchors. Install dry hole marker.	
Spud Date: Rig Release Date:	
hereby certify that the information above is true and complete to the best of my knowledge	e and belief.
At obsert Olive	
	<u>DATE 06/06/2013</u>
Type or print name <u>Stephanie Rabadue</u> E-mail address:	PHONE <u>432-620-6714</u>
For State Use Only	-
APPROVED BY TITLE TITLE TITLE TO A COnditions of Approval (if any).	DATE -6-2013
X	JUN @ 6 2013