

District I – (575) 393-6161

Energy, Minerals and Natural Resources

Revised August 1, 2011

1625 N. French Dr., Hobbs, NM 88240

HOBBS OCD

District II – (575) 748-1283

811 S. First St., Artesia, NM 88210

District III – (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV – (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

JUN 24 2013

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-041-20949
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Armstrong Energy Corporation		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 1973, Roswell, NM 88202-1973		7. Lease Name or Unit Agreement Name Proud Mary
4. Well Location Unit Letter <u>N</u> : <u>810</u> feet from the <u>South</u> line and <u>1830</u> feet from the <u>West</u> line Section <u>32</u> Township <u>5S</u> Range <u>34E</u> NMPM <u>Roosevelt</u> County		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 001092
10. Pool name or Wildcat Wildcat; Fusselman		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
 DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☒
 CASING/CEMENT JOB ☐

OTHER: ☐ Final Abandonment - Location reclamation ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

06-19-13 Disk and re-seeded. Surface reclamation is complete. Location is ready for final inspection.

Spud Date:

07-13-12

Rig Release Date:

08-05-12

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE B. Stubbs TITLE Vice President – Operations DATE 06/20/2013

Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: 575-625-2222

For State Use Only **Accepted for Record Only**

APPROVED BY: ELG 6-24-2013 TITLE _____ DATE _____

Conditions of Approval (if any):

JUN 25 2013



500 North Main Street, Suite 200
P.O. Box 1973
Roswell, New Mexico 88202-1973
(575) 625-2222
Fax (575) 622-2512

June 20, 2013

HOBBS OCD

JUN 24 2013

Oil Conservation Division
1625 N. French Drive
Hobbs, New Mexico 88240

RECEIVED

Re: Proud Mary #1
Township 5 South, Range 34 East, NMPM
Section 32
Roosevelt County, New Mexico

Dear Mr. Gonzales:

Enclosed is a C-103, Subsequent Report, Location Reclamation, for the Proud Mary #1.

If you have any questions, please contact Bruce Stubbs at 505-625-2222.

Sincerely,

ARMSTRONG ENERGY CORPORATION

By: Irma Cunningham
Irma Cunningham, Geo Tech

Enclosure