| Submit 1 Copy To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources District II - (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88210 OIL CONSERVATION DIVISION District III - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION Visitict III - (505) 334-6178 JUN 18 2013 District IV - (505) 476-3460 1220 South St. Francis Dr. District IV - (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505 | | | Form C-103 Revised August 1, 2011 | |
|--|--|--|--|--|
| | | | WELL API NO. 30-005-29159 5. Indicate Type of Lease STATE X FEE - 6. State Oil & Gas Lease No. | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | | 7. Lease Name or Unit Agreement Name Rock Queen Unit 8. Well Number 701 | |
| 2. Name of Operator Celero Energy II, LP | | | 9. OGRID Num | /01 |
| Address of Operator see and the second secon | | | 247128 - 10. Pool name or Wildcat | |
| 3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701 | | | Caprock; Queen | |
| 4. Well Location Unit Letter D : 100 feet from the North line and 1309 feet from the West line Section 36 Township 13S Range 31E NMPM County Chaves | | | | |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4393' GL | | | | |
| 12. Check Appropriate B | ox to Indicate N | ature of Notice, 1 | Report or Othe | r Data |
| NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE COMMINGLE COMMINGLE | | | | |
| OTHER: | | OTHER: MIT | | X |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. | | | | |
| 3/13/13 - MIRU. SITP & SICP = 0#. NDWH & N TOH w/ 93 jts of 2 3/8" IPC tbg & 5 1/2" AS1-X 1 TIH w/ 93 jts (3009') of 2 3/8", 4.7#, 8rd, EUE, J- on/off tool, 1.50" "F" profile nipple & pump off pl off plug at 3019' w/ 8 pts of compression. Release 15 mins with no pressure loss. Pumped down tbg & 300# pressure. | NP pkr. Found 1 pk 55 IPC tbg w/ Glob lug. Tested tbg to 5 from pkr, circ pkr | r rubber missing with be Packer's "A" cond 000# & found no lea fluid, latched back of | th the other 2 pkr lition 5 1/2" AS1- aks. Set pkr from nto pkr & test tbg | rubbers partially torn up. X nickel plated pkr w/ T-2 3009' to 3019' w/ pump -csg annulus to 550# for |
| 3/14/13 - Called Maxie Brown w/ OCD. Ran MIT. Tested for 32 min, starting psi = 560# & ending psi = 560#. No psi loss. Copy of chart & Letter of Violation is attached. | | | | |
| | | | em | ailed to let |
| Spud Date: | Rig Release Da | te: | | |
| I hereby certify that the information above is true and | complete to the be | est of my knowledge | and belief. | <u></u> |
| SIGNATURE KISA Hunt | TITLE <u>Regula</u> | tory Analyst | Ē | DATE_03/22/2013 |
| . ype or print name Lisa Hunt For State Use Only | E-mail address | : <u>lhunt@celeroener</u> | gy.com P | HONE: <u>(432)686-1883</u> |
| APPROVED BY | TITLE DE | t mar | D | ATE 6-18-2013 |
| | | | | UN 2 5 2013 |

.

