

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

**HOBBS OCD** State of New Mexico  
Energy, Minerals and Natural Resources  
**JUN 18 2013**  
**RECEIVED** CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised August 1, 2011

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-05250
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Vanguard Permian LLC		6. State Oil & Gas Lease No. 309623
3. Address of Operator PO Box 1570 281 North NM Highway 248 Eunice, NM 88231		7. Lease Name or Unit Agreement Name Mexico F
4. Well Location Unit Letter B : 660 feet from the North line and 1980 feet from the East line Section 2 Township 15S 37E NMPM County Lea		8. Well Number 5
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3813		9. OGRID Number 258350
		10. Pool name or Wildcat Denton Devonian

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions, Attach wellbore diagram of proposed completion or recompletion.

1. MIRU.
2. POH with pump and rods. Lay down pump and rods.
3. POH with tbg.
4. RJH with CIBP and set @ 12300'.
5. Circulate packer fluid.
6. Pressure test csg to 500# for 30 mins.
7. Well is to be T & A'd.

Rule 19.15.23.14

Set CIBP, RBP or Packer within 100 feet of uppermost  
perfs or open hole Pressure test to 500 psi for 30 minutes with  
a pressure drop of not greater than 10% over a  
30 minute period

The Oil Conservation Division

**MUST BE NOTIFIED 24 Hours**

Spud Date: **Prior to the beginning of operations**

Condition of Approval: notify

OCD Hobbs office 24 hours

Rig Release Date: **prior of running MIT Test & Chart**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Jones TITLE Foreman DATE June 17, 2013

Type or print name Mike Jones E-mail address: mjones@vnrllc.com PHONE: 575-390-4611

For State Use Only

APPROVED BY El Bragah TITLE DIST. MGR DATE 7-3-2013

Conditions of Approval: Notify OCD District office  
24 hours prior to running the TA Pressure Test.

JUL 08 2013