Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	ral Resources	VELL API NO.	Revised August 1, 2011
District III – (505) 334-6178 OCD OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			30-005-00907	
			5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 1 2013 District IV – (505) 476-3460 AUU 0 1 2013 Santa Fe, NM 87505			STATE	FEE X
1220 S. St. Francis Dr., Santa Fe, NM	ŕ			
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM-G-101).FOR SUCH PROPOSALS.)			Lease Name or U	nit Agreement Name
			Rock Queen Unit	
			8. Well Number 101	
1. Type of Well: Oil Well Gas Well Other Injector 2. Name of Operator Gas Well Gas Well			9. OGRID Number	
Celero Energy II, LP			247128	
3. Address of Operator ₄₀₀ W. Illinois, Ste. 1601			10. Pool name or Wildcat	
Midland, TX 79701 4. Well Location			Caprock; Queen	
•	1980 feet from the N	line and 1980	feet from t	the W line
Section 34	antinena e e e e e e e e e e e e e e e e e e			County Chaves
	11. Elevation (Show whether DR,			
12 Chart	only wint of Visata N	atura of Nation Do	mont on Other D	oto
12. Chill bore	nding receip Well licate IV	ature of Notice, Re	port of Other Da	ala
12. Choose only. 12. Choose only. 13. Choose only. 12. Choose only. 14. Choose only. 12. Choose only. 15. Choose only. 12. Choose only. 16. Choose only. 12. Choose only. 17. Choose only. 12. Choose only. 18. Choose only. 12. Choose only. 19. Choose only. 12. Choose only. 14. Choose only. 12. Choose only. 15. Choose only. 12. Choose only. 16. Choose only. 12. Choose only. 17. Choose only.				
Approved tor bond to Subsequat OCD				
Liability (Specification may be to COMPL CASING/CEMEN				
L Plugging) while nm.uslocu			_	
		OTHER:		
OTHER:				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
7/19 - <u>7/30/13</u>				
TIH to 1900', tag up. Worked through & TIH to 2303'. Tag up, could not work through. PU PS & BP. TIH to 2303', could not work through. Circ well w/ PW, but still cold not work through. TIH to bridge @ 2303', re-circ well w/ 45 bbls PW. Psi went from 900#-				
1900# then broke to 0. TOH w/ PS & BP. PU 4.5" impression block. TIH to 2810'. RIH w/ CIBP, could not get down to 2803'. Set				
CIBP @ 2790'. TIH OE & spot 25 sx Class "C" cmt w/ 2% CACL, displace w/ 9 bbls. TOH & WOC. TIH & TAG @ 2598'. CIRC				
WELL W/ 50 BBLS MUD. TEST CSG TO 500# WOULD NOT TEST. TOH & P/U AD-1PKR. TIH TO 2179' & TEST CSG TO 500# OK . CONTINUE TO TEST CSG COMING UP & FOUND LEAK BETWEEN 308' & 371'. TOH W/PKR. SHOOT 4 SPF				
@ 2152'. P/U AD-1 PKR & TIH & SET @ 1745' COULD NOT ESTD INJ RATE INTO PERFS. TOH W/PKR. TIH O/E TO				
2210' & SPOT 40 SX CL "C" W/ 2% CAĈL DISP W/6 BBLS MUD. TOH & WOC. TIH & TAG @ 1963', CIRC MUD TO 1280' TOH. SHOOT 4 SPF @ 1280'. TIH W/ AD-1 PKR & SET @ 995'. COULD NOT ESTABLISH INJ RATE. TOH W/ PKR , TIH				
W/ PS & BP TO 1341'. PUMP 25 SX CL "C" W/ 2% CACL. DISP W/ 3.5 BBLS MUD. TOH & WOC 4 HRS. TIH & TAG @				
1152'. TIH to 425'. Establish circ Dig out & CO WH's. Set P&A ma	on 5 $\frac{1}{2}$ " x 8 5/8". Fill back side & the side we have a star well is now P& A'd	5 $\frac{1}{2}$ " csg to surface w/	265 sx Class"C" w/	2% CACL. NDBOP.
				-
Spud Date:	Rig Release Da	ate:		
L		l		
I hereby certify that the information a	above is true and complete to the b	et of my knowledge o	nd baliaf	
	. /	est of my knowledge a	na bener.	
SIGNATURE	Hun F TITLE Regula	tory Analyst	DATI	E <u>07/31/2013</u>
Type or print name Lisa Hunt For State Use Only	E-mail address	: <u>lhunt@celeroenergy</u>	v.com PHON	NE: <u>(432)686-1883</u>
APPROVED BY: Disting Disting DATE 8-7-2013 Conditions of Approval (if any):				
Conditions of Approval (if any):				
/			AUG 🛛	7 2013 🔨