Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HOBBS OCD

JUN 2 6 2013

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals ECEIVED					NMLC031670B			
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Oth	• 4		8. Well Name and No. SEMU 62					
Name of Operator CONOCOPHILLIPS COMPAN	GERS m		9. API Well No. 30-025-07835					
3a. Address P. O. BOX 51810 MIDLAND, TX 79710 3b. Phone No. Ph: 432-688			(include area code 3/9174)	10. Field and Pool, or Exploratory EUMONT YATES QUEEN			
4. Location of Well (Footage, Sec., T. Sec 20 T20S R38E Mer NMP	·		11. County or Parish, and State LEA COUNTY, NM					
12. CHECK APPE	ROPRIATE BOX(ES) TO IN	NDICATE	NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION TYPE OF ACTION								
☑ Notice of Intent ☐ Subsequent Report			ure Treat	☐ Production (Start/Resume)☐ Reclamation		□ Water Shut-Off□ Well Integrity☑ Other		
☐ Final Abandonment Notice	☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	_	Construction and Abandon Back	☐ Tempor	Recomplete Temporarily Abandon Water Disposal			
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) ConocoPhillips has experieces fluids coming from around the surface after P&A was complete. We would like to perform the following procedure to isolate and fix leak and re-plug. Rig would like to move on ASAP. Procedures: 1) Dig out cellar. Find leak in 5?, 7-5/8? or 10? 2) MiRU. NU BOP. Weld on flanges. Install valves for well control. Install gauges on 5? x 7-5/8 x 10? to monitor pressures 3) Mi reverse unit. Drill out 5? casing to +/- 320?. Monitor well. 4) RIH WL? Perf @ +/- 300?. Set PKR @ 50?. Circ 250sx to surface in 5? x 7-5/8 (x 10? if possible). Close 7-5/8 x 10? surface valve, pump 50sx cmt down 5? into formation. Shut well in under positive pressure overnight.								
-	Electronic Submission #211 For CONOCOPH				n System			
Name (Printed/Typed) RHONDA ROGERS			Title STAFF REGULATORY TECHNICIAN					
Signature (Electronic Submission) D				2013				
	THIS SPACE FOR	FEDERA	L OR STATE	OFFICE U	SE			
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or ertify that the applicant holds legal or equitable title to those rights in the subject lease			Title			Date		
thich would entitle the applicant to conductitle 18 U.S.C. Section 1001 and Fitte 43. States any false, fictitious or and details.	<u> </u>	ne for any pe	Office son knowingly and thin its jurisdiction	l willfully to m	ake to any department or	agency of the	United	

Additional data for EC transaction #211121 that would not fit on the form

- 32. Additional remarks, continued
- 5) Check well in A.M. Fill wellbore.