Form 3160-5 (March 2012)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT:

OCD Hobbs
HOBBS OCD

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014


5. Lease Serial No. NM-6863

SUNDRY NOTICES AND REPORTS ON WELLS 27 2013

Do not use this form for proposals to drill or to re-enter an

6. If Indian, Allottee or Tribe Name

abandoned well.	Use Form 3160-3 (A	PD) for such pr	oposals.				
SUBMI	T IN TRIPLICATE – Other	7. If Unit of CA/Agreement, Name and/or No.					
1. Type of Well		Querecho Plains Queen Asso Sand Unit					
Oil Well Gas W	/ell / Dther Inje	8. Well Name and No. QPQASU #27					
2. Name of Operator Mewbourne Oil Company		9. API Well No. 30-025-24520					
3a. Address 3b. Phone No. (include area code)				10. Field and Pool or Exploratory Area			
PO Box 5270, Hobbs NM 88240 (575) 3				Querecho Planis Queen Associated			
 Location of Well (Footage, Sec., T.,. 1650' FSL & 990' FWL, Sec 27, 1)		11. County or Parish, Lea	State		
12. CHEC	CK THE APPROPRIATE BO	X(ES) TO INDICATE	NATURE OF NOTI		IER DATA		
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Fracture Trea		luction (Start/Resume)	Water Shut-Off ✓ Well Integrity		
Subsequent Report	Casing Repair	New Constru	action Rec	omplete	Other		
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Aba		porarily Abandon er Disposal			
determined that the site is ready for 08/15/13 MIRU WS rig. Blew wel Pumped 160 bbls 2% KCl pkr fluuid WS rig. Mark Whitaker w/NMOCI See attached chart.	l down. ND WH & NU E d down csg. Set pkr @ 35	556'. ND BOP & NU	J WH. Performed	MIT. Tested esg to a back on injection.	t tbg testing to 5000# above slips. 400# for 30 mins, held OK. RDMO		
14. I hereby certify that the foregoing is to	run and correct. Name (Printe	d/Tunad)		/ - w	2 4 2013 AND MANAGEMENT D FIELD OFFICE		
, ,	de and correct. Name (171mee	, ,					
Jackie Lathan	·	Title	Hobbs Regulator	у			
Signature actie	Lathan	Date	08/19/13				
	THIS SPACE	FOR FEDERAL	OR STATE OF	FICE USE			
Approved by			litle		Date		
Conditions of approval, if any, are attached that the applicant holds legal or equitable tientitle the applicant to conduct operations to	itle to those rights in the subjec	s not warrant or certify et lease which would	Office				
Title 18 U.S.C. Section 1004 and Title 43 fictitious or fraudulent statements or representations.	U.S.O. Section 1212, make it a scn) attorios so arry makery hi	crime for any person kn hin its jurisdiction.	nowingly and willfully	to make to any departme	nt or agency of the United States any false.		



Wildcat Measurement Service, Inc.

416 East Main Street P.O. Box 1836 Artesia, New Mexico 88211 Office: (575)746-3481 Toll Free: 1-888-421-9453

Calibration Certificate

Company Nar	ne: <u>L & E Sen</u>	vices			
Recorder Type		VICES		·	,
Recorder Seri			 •		
recorder och	ai. <u># 0000</u>		·		
Recorder Pres	ssure Range: 0	-1000#	Accuracy	+/-: 0.2% F	SIG
	Range:		eg F.		
, omporator o			-9··		
Increasing Pre	essure		Decreasing Pre	essure	
Applied Indicated		Error%	Applied	Indicated	Error%
Pressure	Pressure		Pressure	Pressure	
0.0#	0.0#	0	800#	800#	0
100#		<u> </u>	600#		0
300#	300#		}	<u> </u>	. 0
500#	500#	0			0
700#			0.0#	0.0#	Ō
1000#	1000#	0			·
			<u> </u>	<u> </u>	L
Temperature	Test	1			
	Indicated	Error%	1		
Temperature		L1101 70			
		!	<u>.</u> 		
]		
					•
]		
]		
Certified Calib	ration Instrume	ent Used	1		
Gauge: Crysta			₩,		
	ai	 '	,		
Deadweight:_		 ·	·		
Remarks:					
rtemants					······································
					1
					·
Calibration Da	ite: <u>107/08/28</u>	13	·	•	
Technician:	Vi Si	thehan	\mathscr{L}	Craig Sutherla	ınd
			- (= 5 3 = 1.31.10	•