Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

HOBBS OCD

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals า ดู จุ วการ 5. Lease Serial No. NMNM104050

6. If Indian, Allottee or Tribe Name

3	001 23 2013	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.		7. If Unit or CA/Agreement, Name and/or No. NMNM100723X
1. Type of Well ☐ Gas Well ☐ Other	Kechiari	8. Well Name and No. CORBIN FEDERAL DELAWARE UNIT 17
	STAN WAGNER ner@eogresources.com	9. API Well No. 30-025-30727
3a. Address P.O. BOX 2267 MIDLAND, TX 79702	3b. Phone No. (include area code) Ph: 432-686-3689	10. Field and Pool, or Exploratory WEST CORBIN
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, and State
Sec 18 T18S R33E NENW 660FNL 1980FWL		LEA COUNTY, NM
		<u> </u>

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION					
<ul><li>☑ Notice of Intent</li><li>☐ Subsequent Report</li><li>☐ Final Abandonment Notice</li></ul>	☐ Acidize ☐ Alter Casing ☑ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

EOG Resources requests permission to repair a casing leak as follows:

- Set CBP at 4860'
   Set CBP at +/- 650'
   Set CICR at +/- 560' (20' above casing leak)
- Squeeze 100 sx Class C cement into casing leak.
- Set CBP at 120
- Pump 25 sx Class C cement down 5-1/2" X 8-5/8" annulus. WOC 24 hrs.
- Drill out 5-1/2" production casing through CBP at 120'. Pressure test casing to 500 psi to
- 8. Drill out CICR and CBP at +/- 650'. Pressure test casing to 500 psi to verify squeeze.
- 9. If casing tests good, remove CBP at 4860'.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct.  Electronic Submission #219922 verified by the BLM Well Information System  For EOG RESOURCES, INC., sent to the Hobbs  Committed to AFMSS for processing by JOHNNY DICKERSON on 09/13/2013 ()						
Name(Printed/Typed)	STAN WAGNER	Title	REGULATORY ANALY	ST A	חחחחוורה	
				H	FPNUVLU	,
Signature	(Electronic Submission)	Date	09/12/2013			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			A	OCT 18 2013		
Approved By  Conditions of approval, if ar certify that the applicant hole	ry, are attached. Approval of this notice does not warrant or ds legal or equitable title to those rights in the subject lease	Title			OF LAND IMENIGEME LSBAD FIELD OFFICE	NI NI
	icant to conduct operations thereon.	Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or sautispent statement or representations within its jurisdiction.



## Additional data for EC transaction #219922 that would not fit on the form

## 32. Additional remarks, continued

10. Rih w/ 2-7/8" tubing and place well back on production.

## Corbin Federal Delaware Unit 17 30-025-30727 COG Operating LLC October 18, 2013 Conditions of Approval

Work to be completed by January 18, 2014.

- 1. Must conduct a casing integrity test to 500 psi after casing repair is done. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done. Operator to include new well bore schematic of current well condition when work is complete.

JAM 101813