Submit I Copy To Appropriate District State of New Mexico	Form C-103	
Office <u>District 1</u> – (575) 393-6161 HOBBS OCD L(25) Energy, Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
District II - (575) 748-1283 811 S. First St., Artesia, NM 882102 3 2013 OIL CONSERVATION DIVISION	30 025 31888	
<u>District III</u> ~ (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE	
District IV ~ (505) 476-3460 RECEIVED Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
87505	7. Loose News on Heit Kennen Mense	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Red Hawk 32	
PROPOSALS.)	8. Well Number	
1. Type of Well: Oil Well 🔲 Gas Well 📓 Other SWD	8. Well Number \checkmark	
2. Name of Operator	9. OGRID Number	
BASIC ENERGY SERVICES L.P.	246368	
3. Address of Operator	10. Pool name or Wildcat	
PO BOX 10460 MIDLAND TEXAS 79702	Delaware	
4. Well Location		
	fact from the WEST	
Unit Letter L : 1980 feet from the SOUTH line and 810		
<u> </u>	34E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.		
3643'		
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data	
]	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK _ PLUG AND ABANDON _ REMEDIAL WOR		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR		
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 📋 CASING/CEMEN	Т ЈОВ 🗌 🗸	
	_	
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co 		
proposed completion or recompletion.		
proposed completion or recompletion.		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER.		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER.		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER.		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER.		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER.		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER.		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER.	·	
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE	ge and belief.	
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date:	ge and belief.	
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date:		
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	<u>1GR.</u> DATE_1022/13	
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge	<u>1GR.</u> DATE_1022/13	
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE SIGNATURE DAVID ALVARADO E-mail address: david.alvarado@basicer	<u>1GR.</u> DATE_1022/13	
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	<u>IGR.</u> DATE_1022/13 nergyservices.com PHONE:	
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE SIGNATURE DAVID ALVARADO E-mail address: david.alvarado@basiceer For State Use Only	<u>IGR.</u> DATE_1022/13 nergyservices.com PHONE:	
PLEASE SEE THE ATTACHED SHEET THREE TOTAL ON WORK OVER. REDHAWK IS NOW READY FOR MIT AT YOUR CONVENIANCE Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE SIGNATURE DAVID ALVARADO E-mail address: david.alvarado@basicer	<u>1GR.</u> DATE_1022/13	

OCT 2 4 2013

SUBSEQUENCE REPORT

REDHAWK 32 STATE # 1

API 30 025 31888

1980 FSL 810 FWL

UNIT L, SEC32, T19S, R34E LEA COUNTY NM

- 8-20-13 MI EQUIPMENT RIG UP
- 8-21-13 NU BOP, ENVIRO VAT, TIO WITH DC CLEAN OUT TO 106' SDFD
- 8-22-13 INTEGRATY TEST FOUND LOSS AT 2BPM AT 150 PSI CALL FOR CMT CREW NU CMT CREW PUMP 80 SX CLASS "C" @ 700 PSI BROUGHT CMT TO SURFACE SDFD WOC.
- 8-23, 25-13 WOC
- 8-26-13 POH W/ AD-1 PKR. TIH W/ 4 ¾ CONE BIT W/COLLARS DRILL OUT SQUEËZE TEST TO 400 PSI LOSS OF INTEGRATY IN 15 MIN 60# CALL FOR CMT PUMPED 160 SX SQUEEZED AT 900 PSI SDFN WOC
- 8-27-13 TIH WITH BIT DRILL OUT SQUEEZE TESTED TO 400 PSI LEAKED OFF IN 30 MIN.

PUMP 35SX C AT 300 PSI SDFD WOC.

- 8-28-13 TIH DRILL OUT SQUEEZE TEST 400 PSI LEAKED OFF WAIT ON CMT TRUCK SDFD
- 8-29-13 NU CMT TRUCK PUMP 25SX 3 % CL2 WAIT 1 HR PUMP25SX @ 500 WAIT 30 MIN

PUMP 15SX C 3% CL2 SQUEEZED 1000 PSI SDFN WOC

- 9-3-13 TIH WITH 4 3/4 BIT AND COLLARS DRILL OUT SQUEEZE TEST TO 400 PSI HELD CONTINUE DRILL OUT TO 342 TOP OF CMT FOUND NOT ON RECORD DRILLOUT TO 460.59 TOP OF RECORDED PLUG FOUND METAL MILL AND CONTINUIED DRILL TESTED SHOWED LOSS OF INTEGRATY OF CASING . CASING DAMAGED RAN4 7/8 SWEDGE W / BUMPER SUB AND COLLARS WORKED ON CSG TIL CLEAR / CALL FOR CMT / SQUEEZED WITH 75 SX TO 1500 PSI SDFN WOC.
- 9-4-13 TIH WITH 4 /3/4 BIT 6 COLLARS DRILL OUT SQUEEZE TEST TO 600 PSI HELD CONTINUE TO DRILL INCOUNTER MORE JUNK IN WELL BORE MILL OUT TO 462' CUT CORE TOH WITH CORE SHOE FOUND 2" x 6' PIPE SDFD.
- 9-5, 6, 7,-13 TIH WITH CONCAVE MILL CONTINUE TO MILL ON JUNK TO 521' SDFD.

- 9-9-13 TIH WITH IMPRESION BLOCK TOH TIH WITH CONE BUSTER MILL / MILL TO 537' BACK ON CMT. TOH WITH MILL TIH WITH 4 ¾ BIT COLLARS CONTINUE TO DRILL OUT PLUG TO 600' SDFD.
- 9-10-13 TIH WITH TBG TOP NEXT PLUG @ 1558 ' TOH WITH BIT / TIH WITH AD-1 SET AT 600' TEST CSG TO 1500 GOOD TOH WITH TBG AND PKR / TIH WITH 4 ¾ B IT COLLARS SDFD
- 9-11,26-13 CONTINUE MILLING ON METAL, RUBBER, JUNK IN HOLE FOUND TIGHT SPOT TOH QSEVERAL TIMES TIH WITH SWEDGE CASING DAMAGED TO CASING @ 1650'-1665'TEST CASING TO 1400 PSI GOOD PATTERN OF EACH PLUG SHOWING THE WELL WAS NITRO BLASTED FOR CASING RETREVING
- 9-27-13 CONTINUE MILLING OPERATIONS WITH CONE BUSTER MILL TO 1702' SDFD
- 9-28-13 TOH W/ MILL TIH WITH 4 ¾ BIT COLLARS DRILL OUT REST OF PLUG TO1803' CONTINUE TO NEXT PLUG AT 3064' DRILL OUT CMT TO 3089' TIGHT SPOT @3104' TOH WITH BIT TIH W/ COLLARS BUMPER SUB AND SWEDGE WORK TIGHT SPOT GOOD. TOH WITH SWEDGE TIH WITH BIT AND COLLARS SDFN.
- 9-30-13 TIH WITH CONE BUSTER MILL TO 3104 CONTINUE TO MILL ON METAL 3106 TOH WITH MILL TIH WITH CORE CUTING SHOE WITH JUNK BASKET. SDFD
- 10-1, 2-13 CUT 4' @ 3110' CORE CAME OUT WITH PIPE PEACES TIH WITH CORE CUTTER TOH WITH MORE PEACES OF PIPE @3120' CMT ON BTM OF CORE SDFD
- 10-3-13 TIH WITH BIT COLLARS TO 3120 DRILL OUT PLUG FALL TO NEXT PLUG @ 4506' DRILL TO 4510' HIT METAL TOH WITH BIT TIH W CORE CUTTER RETREVED JUNK METAL 4514' SDFD
- 10-4-13 TIH WITH 4 ¾ BIT DRILL OUT PLUG TO TOP OF CMT @ 5292.88' DRILL OUT TO 5298' HIT METAL TOH WITH BIT TIH WITH CONCAVE MILL. MILL TO 5305'RETURN SHOWS CMT SDFD
- 10-5, 6, 7, 8-13 DRILL OUT TO TD @ 8207.95' CIRCULATE HOLE WITH FRESH WATER CALL FOR WIRE LINE TO SET CIBP. TOH WITH PIPE, COLLARS AND BIT LAY DOWN ON RACK.
- 10-9-13 RU WIRE LINE RUN CCL WITH GAMA RAY SET CIBP @7800' BAIL DUMP 25' CMT ON TOP. COROLATE WITH DENSITY LOG RIH WITH PERF GUNS AT (7556-7504). (7484-7406), (7392-7376), (7344-7322), (7304-7286), (7277-7256), (7242-7226), (7218-7110), (7068-7000), (6986-6900), (6876-6800) 2SPF SET COMPOSITE PUG AT 6790'
- 10-10-13WITH ALL THE PROBLEMS WITH THIS WELL BORE NOT TO BE TRUSTED DUE TO NITRO
CUTTING ELECTED TO RUN 6,782' 4 ½ 11.6# FL-4S FLUSH JOINT CSG. SDFN
- 10-12-13TIH WITH CSG HUNG ON SLIPS CALL FOR BASIC CMT CREW OUT OF MIDLAND PUMP
CLASS H WITH ADDATIVES TO SURFACE 15sx EXCESS.WOC SDFN.

- 10-14-13TIH WITH 3 7/8 BIT ON 2 3/8 TUBING DRILL OUT WIPER PLUG/ FC/ FS AND COMPOSITEPLUG CONTINUE TO TOP OF CMT TD 7780' CIRCULATE TWICE CAP. SDFD
- 10-17-13 TIH WITH TREATING PKR SET @ 6769' TEST TO 300# PSI ANULUS GOOD RU ACID CREW ESTABLISH RATE AT 2.75 BPM TO 3 BPM LEAD WITH 24 BBLS FRESH THEN 10 STAGES OF 1000 GAL 15% W/500# ROCK SALT CONTINUE RATE AT 2.75 TO 3 BPM RATE AT REGULATED 1300 TO 1400 PSI. ISP @ 1000 PSI, 5MIN @ 900PSI, 30 MIN 500 PSI,
- 10-18-13 OPEN WELL ZERO PSI ON WELL TOH WITH PKR LAY DOWN WORKING STRING WAIT ON NEW 2 7/8 SLIM HOLE PCT SDFN.
- 10-21-13 TIH WITH 4 ½ X 2 7/8 ARROW SET NICKLE PLATED W/O&O TOOL W/PROFILE NIPPLE SET @ TOP OF PKR 6760'BTM OF PKR @ 6767.9 SET IN COMPRESSION 15 POINTS.
- 10-22-13 WELL READY FOR MIT.

	Current	10/22/2013		
Basic Energy Services LP				
Red Hawk 32 State # 1				
1980' FSL, 810' FWL, Unit (L), Sec 32, T19S, R34E Lea Co	D.			
API # 30-025-31888				
	a sector and a sector and	Tree Connection	2 7/8" J-55 PCT slim hole	
		257		
	50 8 8 6 9 4 7 1 8 9 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9			
		- 容疑()		
		A State of the second s		
		1 9 9 9 4		
		Surface Casing:	13 3/8" 54.5#	
Surface Hole				
Bit Size 17 1/2"		Setting Depth @	525' 500sx	
			Circulated to Surf	
		1	Existing	
		1		
Inter, Hole		Interm. Casing:	8 5/8" 32#	
Bit Size 12 1/4"		[
		Setting Depth:	5,241' 3,250sx DV @ 3,485'	
			Circulated to Surf.	
Packer Set @ 6,750'			Existing	
Packer 5 1/2" X 2 7/8" AS1-X(NP) (SS) 2.25" "F"			-	
2 7/8" T-2 on/off tool SS top NP btm.		Perforation Intervals	as Follows:	
		(6,800'- 6,876'), (6,900	(6,800'- 6,876'), (6,900'- 6,986'), (7,000'-7,068')	
		(7,110'-7,218'), (7,226'-7,242'), (7,256'-7,277')		
Cement Data:		(7,286'-7304'), (7,322'	(7,286'-7304'), (7,322'-7,344'), (7,376'-7392')	
		(7,406'-7,484'),(7,504'	-7,556') Net pay 556'	
Lead -				
		Set CIBP @7,800 + 25	5'cmt. on top	
Tail -				
		Existing plug @ (8,01	12' - 8315')	
Note -				
		CIBP @ 10,050' + 35' Cmt.		
· · · · · · · · · · · · · · · · · · ·	- 74	PBTD:	13,568"	
		Liner Csg.:	4 1/2" 11.6 # New	
Ditaina 7.7/01		Sotting Darth @	6700'	
Bit size 7 7/8"		Setting Depth @	6782' Circulated to Surf	
<u> </u>			Unculated to Juli	
		Production Csg.:	5 1/2" 17# Existing	
		Frounction csy.:	5 1/2" 17# Existing	

Setting Depth @ <u>13,658'</u> <u>1,850sx</u> DV @ 9,633' Circulated to Surf Existing

.