Submit 1 Copy To Appropriate District State of New Office		Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resources District II – (575) 748-1283 OUL CONSERVATION DIVISION		Revised August 1, 2011
		30-025-34499
811 S. First St., Artesia, NM 88210 District III $-(505)$ 334-6178 007, 2, 3, 2013 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE X FEE
$\frac{\text{District III}}{1000 \text{ Rio Brazos Rd., Aztec, NM(87410}} 2 3 2013 $ $\frac{1220 \text{ South St. Francis Dr.}}{\text{Santa Fe, NM 87505}}$		STATE X FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		COOPER, J.W.
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well X Gas Well Other		009
2. Name of Operator CIMAREX ENERGY CO. OF COLORADO		9. OGRID Number 162683
3. Address of Operator		10. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701 JALMAT; TAN-YATES-7RVRS (0) 4. Well Location ////////////////////////////////////		JALMAT, TAN-TATES-/RVRS (OIL)
Unit Letter 1: 1650 feet from the SOUTH line and 660 feet from the EAST line		
Section 14 Township 24	S Range 36E	NMPM LEA County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3,331' - GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK D ALTERING CASING		K 🛛 ALTERING CASING 🗌
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PANDA		
PULL OR ALTER CASING I MULTIPLE COMPL CASING/CEMENT JOB /		
_		
OTHER: OTHER: WELL PLUGGED AND ABANDONED 10/15/13.		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
10/12/13: PUMP 30 SXS. CMT. W/ 2% CACL @ 3,000' (OK'D BY NMOCD); WOC X TAG CMT. PLUG @ 3,020'; PUMP 60 SXS.		
CMT. @ 3,020' (PER NMOCD); WOC. 10/14/13: TAG CMT. PLUG @ 2,697'; CIRC. WELL W/ PXA MUD; PRES. TEST 5-1/2" CSG. TO 750# - HELD OK; PUMP 70		
SXS. CMT. W/ 2% CACL @ 1,270'; WOC X TAG CMT. PLUG @ 685'; PERF. X CIRC. TO SURF., FILLING ALL		
ANNULI, 70 SXS. CMT. @ 200'-3'.		
10/15/13: DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. ON ALL ANNULI; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.		
Snud Date: MIRU 10/10/13 Pig Palao	RDMO 10/1	5/13
Spud Date: Rig Release	se Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE DUCATION TITLE: AGENT		DATE: 10/21/13
Type or print name: DAVID A. EYLER E-mail address: DEYLER@MILAGRO-RES.COM PHONE: 432.687.3033		
For State Use Only		
APPROVED BY: Conditions of Approval (if any):		
APPROVED BY: Conditions of Approval (if any):		
l		OCT 2 4 2013 X