

Submit One Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

HOBBS OCD

OCT 31 2013

RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103  
Revised November 3, 2011

WELL API NO. <b>30-025-34323</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>MONUMENT 235 STATE</b>
8. Well Number <b>#19</b>
9. OGRID Number <b>20070 4303</b>
10. Pool name or Wildcat <b>MONUMENT ABO</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3703</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: ☐ Oil Well ☐ Gas Well ☐ Other  
2. Name of Operator **USA INC.**  
**CHEVRON MIDCONTINENT L.P.**  
3. Address of Operator  
**15 SMITH ROAD MIDLAND TX 79705**  
4. Well Location  
Unit Letter **M** : **753** feet from the **S** line and **637** feet from the **W** line  
Section **23** Township **19S** Range **34E** NMPM County **LEA**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

☒ Location is ready for OCD inspection after P&A

- ☐ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  
☐ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  
☐ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR  
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR  
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- ☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.  
☐ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.  
☐ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.  
☐ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)  
☐ All other environmental concerns have been addressed as per OCD rules.  
☐ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.  
☐ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Bill Beck TITLE EMC-Construction Rep. DATE \_\_\_\_\_

TYPE OR PRINT NAME Bill Beck E-MAIL: WADS@chevron.com PHONE: 575-390-1411  
For State Use Only

Mark Whitaker Compliance Officer 10/30/2013

NOV 21 2013