State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE CONSERVATION DIVISION	10,70020 27 2007
FILE IN TRIPLICATE DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-27060
DISTRICT III Santa Fe, NM 87505 Santa Fe, NM 87505 DISTRICT III	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 RECEIVED	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	North Hobbs (G/SA) Unit Section 31
1. Type of Well:	8. Well No. 312
Oil Well Gas Well Other Injector X	
2. Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323	10. Pool name or Wildcat Hobbs (G/SA)
4. Well Location	
15 1100 110111 1500	t From The <u>East</u> Line
Section 31 Township 18-S Range 38-E	NMPM LEA County
3651' KB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Charles of National Report (National Report Repor	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ADANDON ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB	
	- JOB []
Thigh Cashing Trossare	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. RUPU&RU. 2. ND wellhead/NU BOP. During this procedure we plan to use	
2 Determine failure and renoir	•
4. RBIH with injection packer and equipment 5. ND BOP/NU wellhead. the closed-loop system with a steel tank and haul contents to the required	
6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. 7. RDPU & RU. Clean location and return well to injection disposal per ODC Rule 19.15.17	
7. RDPO & RO. Clean location and return well to injection	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or	
closed according to NMQCD guidelines , a general permit or an (attached) alternative OCD-approved plan	
SIGNATURE TITLE Injection Well Analyst DATE 11-25-2013	
TYPE OR PRINT NAME Robbie Underhill E-mail address: Robert Underhill@oxy.com	
For State Use Only Male 2M RACE TO 1	
CONDITIONS OF APPROVAL IF ANY	
V .	
	TUEL 0 3 2013