Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161 HOBBS	Minerals and Natural Resources	August 1, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210	MACONSERVATION DIVISION	30-025-10538
District III - (505) 334-6178	CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505		307841
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION F		7. Lease Name or Unit Agreement Name Skelly Penrose B Unit
<u></u>	II 🛛 Other	8. Well Number 008
2. Name of Operator Providence Energy Services, Inc. dba Kelton Operating		9. OGRID Number 01244
3. Address of Operator		10. Pool name or Wildcat
POBox 928, Andrews, Texas 79714-0928		Langlie Mattix (37240)
4. Well Location		
Unit Letter <u>J : 1980</u>	feet from the _S line and	
		NMPM County Lea
11. Ele	evation (Show whether DR, RKB, RT, GR, etc.	:.)
12 Check Appr	ste Nature of Notice	Papert or Other Data
PERFORM P Plugging of well bore only NOTICE of well bore only NOTICE of well bore only NOTICE of well bore only Performed for plugging of well bore only Performed for plugging of well bore only NOTICE of well bore only Performed to the property of	ate Nature of Notice,	Report of Other Data
PERFORM P Plugging of well bore ding of plugging discrete	not of views	SSEQUENT REPORT OF:
PERFORM P Plugging retained the	Web Pag	
TEMP proved for bond is Subsequat Occ	COMMENCE DE	RILLING OPNS. D P AND A
Application and be found	☐ CASING/CEMEN	
OTI Plugging) which may OTI under forms! 13! www.emnrd.state.nm.uslocd www.emnrd.state.nm.uslocd OTI under forms! yww.emnrd.state.nm.uslocd		_
OTI Plugging) What Plugging What		
OTI under formed state.	OTHER;	
13sed or completed oper	ations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
any proposed work). OLL	RULE 19.15.7.14 NMAC. For Multiple Cor	npletions: Attach wellbore diagram of
proposed completion or recompletion		
12/03/13 MIRU plugging equipme	ent. 12/04/13 Dug out cellar. RIH w. tbg a	nd tagged CIBP @ 3505. Circulated hole
w/mud laden fluid. Spotted 25 sx	cement @ 3505-3305. POH to 2569'. Spott	ed 125 sx cement @2569-1350. POH w/
tbg. WOC. 12/05/13 Shut down f	or weather. 12/09/13 Tagged plug @ 1347	". Perf'd csg @ 1300'. Pressured up on
csg. Spotted 25 sx cement @ 1347	'-1250 (per Mark Whitaker). POH w/ tbg.	Perf'd csg @ 378'. Pressured up on csg to
700 psi. Spotted 30 sx cement @ 4	138-surface (per Mark Whitaker). ND BOI	P. Rigged down and Moved off. 12/17/13
	ig out cellar. Cut off wellhead. Weldedon A	Above Ground Dry Hole Marker.
Removed deadmen and cleaned lo	cation. Moved off.	
Spud Date:	Rig Release Date:	•
		ì
paraby cartify that the information above is to		
iereby certify that the information above is the	To and complete to the heat of I I do	1 - 1: - C
	rue and complete to the best of my knowledge	e and belief.
GNATURE		
07 1-16-	TITLE RUSIDENT	DATE 12-23-2013
ype or print name C. Dale LEU		DATE 12-23-2013 energy phone: 432-661-1364
ype or print name Dale LET	TITLE RUSIDENT	DATE 12-23-2013
or State Use Only Mal. 1718	TITLE RUSIDENT	DATE 12-23-2013 energy PHONE: 432-661-1364
ype or print name C. Dale LEU	TITLE RUSIDENT	DATE 12-23-2013 energy PHONE: 432-661-1364