

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

HOBBS OGD

OIL CONSERVATION DIVISION

FEB 03 2014

220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03227
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> - Injection		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator State of New Mexico formerly Xeric Oil & Gas Corp.		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, New Mexico 88240		7. Lease Name or Unit Agreement Name West Pearl Queen Unit
4. Well Location Unit Letter N : 660 feet from the South line and 1980 feet from the West line Section 28 Township 19S Range 35E NMPM County Lea		8. Well Number 125
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 25482
		10. Pool name or Wildcat Pearl Queen

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/03/13----MIRU.

12/04/13----Bleed off well & could not get well to stop flowing. Mixed MLF & pump 80 bbls into well - flow stopped.

12/09/13----Pulled on tbg & could not get tbg unstuck, circulated fresh water to dissolve salt rings was able to pull tbg & pulled 140 jts out of well. RIH w/ 154 jts Tag CIBP @ 4635' - circulated well w/ 100 bbls MLF & spot 25 sxs.

12/10/13----Tag cmt @ 4340'. Perf @ 3270' - sqz 25 sxs displaced cmt to 3170'.

12/11/13----Tag cmt @ 3080'. Perf @ 1835' - sqz 25 sxs WOC & Tag @ 1872' tag low sqz 25 sxs.

12/12/13----RIH & Tag @ 1301'. Perf @ 352' - sqz 100 sxs to surface. RDMO.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE P&A Tech DATE 01/11/14

Type or print name Greg Bryant E-mail address: _____ PHONE: 432-563-3353

For State Use Only

APPROVED BY:  TITLE Compliance Officer DATE 02/03/2014

Conditions of Approval (if any):

FEB 03 2014