State of New Mexico

Energy, Minerals and Natural Resources Department

For	m C-103	
Rev	ised 5-27-20	0

FILE IN TRIPLICATE	HOBBS OUL C	CONSERVATION DIVISION	Revised 5-27-2004		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	FEB 1 4 2014	1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-07545		
DISTRICT II		Santa Fe, Title 57565	5. Indicate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210	RECEIVED		STATE X FEE		
DISTRICT III	BECT.		6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410	IOMIODO ANID DEDO	DEC ON WELL C	7. Lease Name or Unit Agreement Name		
	NOTICES AND REPO		· /		
l ,		OR TO DEEPEN OR PLUG BACK TO A RMIT" (Form C-10+) for such proposals.)	North Hobbs (G/SA) Unit Section 33		
1. Type of Well:			8. Well No. 231		
Oil Well	Gas Well	other Injector			
Name of Operator Occidental Permian Ltd.	/		9. OGRID No. 157984		
3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)		
HCR 1 Box 90 Denver City,	ΓX 79323				
4. Well Location			/		
Unit Letter K : 2310	Feet From The	South Line and 1320 Fe	et From The West Line		
Section 33	Township	18-S Range 38-	E NMPM Lea County		
	11. Elevation (Show 3645' KB	v whether DF, RKB, RT GR, etc.)			
Pit or Below-grade Tank Application					
Pit Type Depth of Gro		Distance from nearest fresh water well			
Pit Liner Thickness mil	Below-Grade Tank	Volume bbls; Construction Ma	aterial		
12. Ch	eck Appropriate Box t	to Indicate Nature of Notice, Report, or	Other Data		
	ITENTION TO:		SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABAND	OON REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PNS. PLUG & ABANDONMENT		
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEME	NT JOB		
OTHER:	j Manapie Completion	<u> </u>			
		Colleg tubil	<u>isjee</u>		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
1. RU coiled tubing unit.					
2. RIH and clean out to 4250'. Pull up to 4200'. Ran perf clean tool and water wash perfs @4042-4230'.					
3. Pump 10 bbl gel sweep.					
4. Wash perfs 4042-4230' w/2500 gal of 15% NEFE acid.5. Pump 10 bbl gel sweep. Circulate clean.					
6. POOH and RD coiled tubing unit.					
7. Return well to injection.					
RU 11/26/2013					
RD 11/26/2013					
I hereby certify that the information above constructed or	is true and complete to the	best of my knowledge and belief. I further certify	that any pit or below-grade tank has been/will be		
closed according to NMOCD guideling	es , a general	permit or an (attached) alternative	e OCD-approved		
The state of the s					
SIGNATURE Manistrative Associate DATE 02/13/2014					
TYPE OR PRINT NAME Mendy A. Johnson De-mail address: mendy_johnson@oxy.com TELEPHONE NO. 806-592-6280					
APPROVED BY Major De State Use Only Major De State Use Only Major De State Use Only APPROVED BY					
ATTROVED BY					
CONDITIONS OF APPROVAL IF ANY ()					

FEB 2 0 2014