OIL CONSERVATION DIVISION - Hobbs office Must Be Notified 24 hours prior to the beginning of Plugging Operations.

.1	Amache	LEASE NAME WELL # API # COUNTY	325 30-025-06349
	WELL BORE INFO.	ezneg goeso	
0	17 1/4" Hole 12 3/4" 50# @ 287' w/ 300 sx to surf		
801			
1603	TOC @ 1375' (TS)		
2404	11" Hole		
3205	8 5/8" 28# @ 3049' w/ 1100 sx TOC @ 1375' (TS) TOC @ 3075'		
4007			
4808			•
5609 6410			
<b>∪</b> +10	CIBP @ 6557' w/ no cmt CIBP @ 6850' w/ 2 sx cmt		Drinkard perfs @ 6602'-6778'
7212	CIBP @ 7600' w/ 1 sx cmt		Abo perfs @ 6928'-7270'
8013	7 7/8" Hole 5 1/2" 15.5/20# @ 8012' w/ 925 sx TOC @ 3075'	PBTD @ 6557' TD @ 8013'	McKee perfs @ 7615'-7800' Connell perfs @ 7925'-7955'

· A	<i>∕</i> ≈7
VI VI USEU	ك لما لاما كما

**LEASE NAME** WELL# API# COUNTY **NEDU** 325

30-025-06349 LEA

## **WELL BORE INFO.**

0

17 1/4" Hole

801

1603

2404

3205

4007

4808

11" Hole 8 5/8" 28# @ 3049' w/ 1100 sx TOC @ 1375' (TS)

TOC @ 3075'

CIBP @ 6557' w/ no cmt

CIBP @ 6850' w/ 2 sx cmt

TOC @ 1375' (TS)

12 3/4" 50# @ 287' w/ 300 sx to surf

PROPOSED PROCEDURE

PUH & perf @ 337' & sqz 225 sx Class "C" cmt & attempt to CIRC 5 1/2" & 8 5/8" to surf. (Shoe & Water Board)

PUH & perf @ 1440' & attempt to sqz 200 sx Class "C" cmt from 1440'-1150' WOC/TAG (Top of Salt)

 PUH & perf @ 3125' & attempt to sqz 200 sx Class "C" cmt from 3125'-2350' WOC/TAG (Shoe, Yates & Base of Salt)

2. PUH & spot 25 sx Class "C" cmt from 5400'-5150' (Grayburg)

 MIRU P&A unit, RIH w/tbg, verify CIBP & CIRC w/ MLF, and spot 30 sx Class "C" cmt from 6557'-6257' WOC/TAG (CIBP & Tubbs)

Drinkard perfs @ 6602'-6778'

Abo perfs @ 6928'-7270'

McKee perfs @ 7615'-7800' Connell perfs @ 7925'-7955'

PBTD @ 6557 TD @ 8013'

5609

6410

7212

CIBP @ 7600' w/ 1 sx cmt 7 7/8" Hole 5 1/2" 15.5/20# @ 8012' w/ 925 sx TOC @ 3075'

8013