

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-24399
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other SWD <input checked="" type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator RICE OPERATING COMPANY		6. State Oil & Gas Lease No. SWD-046
3. Address of Operator 122 W TAYLOR, HOBBS, NM 88240		7. Lease Name or Unit Agreement Name BLINEBRY DRINKARD
4. Well Location Unit Letter C : 660 feet from the NORTH line and 2305 feet from the WEST line Section 2 Township 22S Range 37E NMPM LEA County		8. Well Number 002
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3358' GL		9. OGRID Number 19174
		10. Pool name or Wildcat SWD; SAN ANDRES

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: MIT ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

HOBBS OCD

MAR 28 2014

RECEIVED

Summit Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Isaac Juarez TITLE Foreman DATE 3-6-14

Type or print name Isaac Juarez E-mail address: ijuarez2@riceswd.com PHONE: 575-631-0959

For State Use Only

APPROVED BY: Brian Sanchez TITLE Staff Manager DATE 3-28-14

Conditions of Approval (if any):

MAR 31 2014

PRINTED IN U.S.A.

5

6 PM

HOBBS OGD

MAR 28 2014

RECEIVED

03-06-2014

DATE
BR 2221

BD
C-2



FINAL
3360 PSI

RICE OPERATING
Blind by - Drunkard

30-025-2435 SWD #2

UL-9.8-2225 R375
Mach WO
OGD

NOON

MIDNIGHT

6 AM