Submit 1 Copy To Appropriate Distr	State of New Me	xico	Form C-103
Office District 1 - (575) 393-6161 Energy, Minerals and Natural Resources		ral Resources	/ Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 882# OBBS OCD			WELL API NO
District II - (575) 748-1283 OH CONSEDVATION DIVISION		DIVISION	30-025-27059
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	APR 2 9 2014 1220 South St. Fran		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87-	410	ł	STATE 🛛 FEE 🗌
District IV (505) 476 2460	Santa Fe. NM 8/	(505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NN 87505	4 RECEIVED		:
	NOTICES AND REPORTS ON WELLS		7 Logge Name on Heit Agreement Name
	PROPOSALS TO DRILL OR TO DEEPEN OR PLU	1	7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Section 30
PROPOSALS.)			8. Well Number 422
1. Type of Well: Oil Well	Gas Well Other -injector	<u> </u>	/
2. Name of Operator			9. OGRID Number: 157984
Occidental Permian Ltd.			<u> </u>
3. Address of Operator	774 7000		10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City,	TX 79323		·
4. Well Location			
Unit Letter H: 1520 feet from the North line and 1300 feet from the East line			
Section 30 Township 18S Range 38E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	3662' KB		
			Intelligence and the second se
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE O	F INTENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLIN			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
I) POOL 34 Continu			
1) POOH with injection equipment			
2) Clean out to 4278'			cedure we plan to use
3) Squeeze Zn 2C perfs During this pro 4) Drill out CICR & cmt, clean out to PBTD @4278' the closed-loo			system with a steel
4) Drill out CICR & cmt, clean out to PBTD @4278' the closed-loc 5) Perf per prog tank and haul			ontents to the required
6) Acid treat per prog disposal per O			C Pulo 10 15 17
 6) Acid treat per prog 7) RJH with injection assembly per Robbie Underhill 			
8) Return well to injection			
o) Retain wente injection			
Spud Date:	Rig Release Dat	te:	
<u> </u>			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
TIME I STATE ADDITE			
SIGNATURE TITLE Injection Well Analyst DATE 4/22/14			
Type or print name Robbie Underhill E-mail address: Robert_Underhilll@oxy.com PHONE: 806-592-6287			
For State Use Only A A			
Wal Mka			
APPROVED BY: 1 CHUNCH TITLE DIST Supervisor DATE 4/29/2014			
Conditions of Approval (if any)			
APR 3 n 2014			
			U 2014