State of New Mexico Energy, Minerals and Natural Resources Department

,
Revised 5-27-2004
Form C-103

FILE IN TRIPLICATE OIL CONSERVATION DIV	VISION	
DISTRICT I 1220 South St. Francis Dr.		
1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD Santa Fe, NM 87505	30-025-07610	
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210	5. Indicate Type of Lease STATE FEE X	
1301 W. Grand Ave, Artesia, NM 88210 DISTRICT III	6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410		
SUNDRY NOTICES AND BEPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such propo		
1. Type of Well: Oil Well Gas Well Other Injector	8. Well No. 32	
2. Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984	
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)	
HCR I Box 90 Denver City, TX 79323 4. Well Location		
Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line		
Section 4 Township 19-S Range 38-E NMPM Lea County 11. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Elevation (Show whether DF, RKB, RT GR, etc.) 11. Elevation (Show whether DF, RKB, RT GR, etc.)		
3614' KB		
Pit or Below-grade Tank Application or Closure Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT		
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB		
OTHER: OTHER: Coiled tubing job		
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 		
 RU coiled tubing unit. RIH and clean out to 4242'. Pull up to 4115'. Ran perf clean tool and water wash perfs @4120-4198'. Pump 10 bbl gel sweep. Wash perfs from 4120-4198' w/2500 gal of 15% NEFE acid. Pump 10 bbl gel sweep. Circulate clean. POOH and RD coiled tubing unit. Return well to injection. 		
RU 05/29/2014 RD 05/29/2014		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or		
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan		
SIGNATURE MINOLY A CHARACTER TITLE Administrative Associate DATE 06/10/2014		
TYPE OR PRINT NAME Mend A Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO. 806-592-6280		
For State Use Only		
APPROVED BY MALERANY: TITLE D	ist. Supervisionare 6/16/2014	

#JUN 16 2014