
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE HOBBS OCOLL CONSERVATION DIVISION	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 JUL 01 2014 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-05499
DISTRICT II	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE X FEE
DISTRICT III RECEIVED	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 25
1. Type of Well: Oil Well Gas Well Other Injector	8. Well No. 441
Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location	
	t From The <u>East</u> Line
Section 25 Township 18-S Range 37-E	NMPM Lea County
3667' DF	
Pit or Below-grade Tank Application or Closure	·
Pit Type Depth of Ground Water Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Mat	terial
12. Check Appropriate Box to Indicate Nature of Notice, Report, or C	Other Data
The check appropriate Box to maleule of rolles, report, or c	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF: ALTERING CASING
	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING NS. PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUDING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integr	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB Trity Test X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUDING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test , including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates)	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed or	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPPORTUGE OF ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103.	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPPORTUGE OF ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPPORTUGE OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes Witnessed: NO	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPPORTUGE OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTURE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes Witnessed: NO	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Date of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes Witnessed: NO I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify to constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any completion or recompletion. that any pit or below-grade tank has been/will be e OCD-approved
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integr 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes Witnessed: NO Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB rity Test x including estimated date of starting any completion or recompletion. that any pit or below-grade tank has been/will be e OCD-approved
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integ 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes Witnessed: NO Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines a general permit or an (attached) alternative plan SIGNATURE MULTIPLE Administrative	ALTERING CASING NS. PLUG & ABANDONMENT TIT JOB Trity Test In including estimated date of starting any completion or recompletion. That any pit or below-grade tank has been/will be E OCD-approved Associate DATE 06/27/2014
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPPOLIC OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes Witnessed: NO I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy Johnson E-mail address: mendy_johnson@oxy.com For State Use Only	ALTERING CASING NS. PLUG & ABANDONMENT TIT JOB Trity Test In including estimated date of starting any completion or recompletion. That any pit or below-grade tank has been/will be The OCD-approved Associate DATE 06/27/2014 TELEPHONE NO. 806-592-6280
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPPOLIC OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Integrations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of Complete of Test: 06/11/2014 Pressure Readings: Initial – 710 PSI; 15 min – 710 PSI; 30 min – 710 PSI Length of test: 30 minutes Witnessed: NO I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TYPE OR PRINT NAME Mendy Johnson E-mail address: mendy_johnson@oxy.com For State Use Only	ALTERING CASING NS. PLUG & ABANDONMENT TIT JOB Trity Test In including estimated date of starting any completion or recompletion. That any pit or below-grade tank has been/will be E OCD-approved Associate DATE 06/27/2014 TELEPHONE NO. 806-592-6280

JUL 1 4 2014

1



American Valve & Meter, Inc. 1113 W. Broadway P.O. Box 166 Hobbs New Mexico 88240

To: _Pate Trucking				Date_04/09/14		
This is to	certify that:				 	
I_Bud CollinsTechn			an for American Valve	& Meter Inc. ha	s checked	
the calib	ration of the f	ollowing instrument	.			
8" pressure recorder_				Serial No. MFG3219		
at these	points.					
	Pressure	ŧ	Pressure # or Temperature*			
Test	Found	Left	Test	Found	Left	
- 0	- 0	- 0	-	-	-	
- 500	-	- 500	-	-	-	
- 700	-	- 700	-	-	-	
- 1000	-	- 1000	-	-	-	
- 200	-	- 200	-	-	. -	
- 0	-	- 0	-	-	. •	
Remarks					_,	
		•			_	

Signature Mul bollows