Submit 3 Copies To Appropriate District Office District 1 1625 N. French Dr., Hobbs, NM 88240 District II	Form C-103 Revised March 25, 1999 WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 OIL CONSERVATION DIVISION HOBSS OC220 South St. Francis Dr. Santa Fe, NM 87505	30-025-30977 5. Indicate Type of Lease STATE ☑ FEE □ 6. State Oil & Gas Lease No. V-2199
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION-FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Disposal TAJT	7. Lease Name or Unit Agreement Name: Gem, 8705 JV-P
2. Name of Operator BTA Oil Producers 3. Address of Operator	8. Well No. 3 9. Pool name or Wildcat
	9. Poor name of windcat
Unit Letter O: 660 feet from the south line and 1980 feet from the east line	
Section 2 Township 20S Range 33E NMPM Lea County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3579' GR	
11. Check Appropriate Box to Indicate Nature of Notice NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WO	BSEQUENT REPORT OF:
TEMPORARILY ABANDON	RILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST A COMPLETION CEMENT JOB	
	pack and open new interval, same pool
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
recompilation. 8/21 - 9/04/2013 BTA Oil Producers plugged back from the current Delaware perforations and opened a new Delaware interval:	
 MI and set frac tank. Bleed dn well. MI and RU PU. ND WH. NU BOP. Rel pkr and POH. LD tbg. MI work string. RIH w/scraper and bit for 5-1/2" csg to 7752'. POH. MI WL. RIH w/CIBP for 5-1/2" 20 & 23# csg. Set CIBP at 7650'. Cap w/ 40 ft of cmt. RIH w 3-1/8" csg gun loaded w/4 JSPF w/ prem charges. Correlate to Schlumberger LD CNL dated 11/22/90. Perf 6618 to 6648'. RIH w/5-1/2" pkr on 2-7/8" work string. RIH to 6646'. Load hole and spot 100 gal 15% HCL acid over perfs. Raise pkr to 6440'. Set pkr. 	
 Break dn perfs @ 1950 psi. Pmp 1500 gal 15% HCl NeFe. Flush to perfs w/prod wtr. Avg 5 BPM, 2123 psi. Max 5 BPM, 2375 psi. Swab back load to clean up perfs. RU pmp truck. Pmp 200 bbls prod wtr dn tbg @ 2.5 BPM w/press steady @ 1150 psi. PU 5-1/2" x 2-3/8" nickel plated lok-set pkr. RIH w/2-7/8" tbg. Set pkr @ 6563. Circ hole w/pkr fluid. Press test to 500 psi for 30 	
min – good test. ND BOP. NU WH. 11. Place well on injection. $R - 13722$	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE # DATE 09/13/2013	
Type or print name Pam Inskeep pinskeep@btaoil.com	Telephone No. (432) 682-3753
APPPROVED BY Maley Brown TITLE Dist. Supervisor DATE 7/15/2014 Conditions of approval, if any. JUL 17 2014	
•	1

