Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD	Hobbs
-----	-------

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.	
NMLC067230	
6. If Indian, Allottee or Tril	be Name

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.		NMLC0			
		6. If Indian,	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.		7. If Unit or	7. If Unit or CA/Agreement, Name and/or No.		
Type of Well				8. Well Name and No. FEDERAL 3 2	
Name of Operator Contact: SHERRY L. ROBERTS     MARSHALL & WINSTON INC E-Mail: sroberts@mar-win.com		9. API Well 30-025-	No. 25701-00-S1		
3a. Address 3b. Phone No. (include area code)			10. Field and	d Pool, or Exploratory	
MIDLAND, TX 79710-0880		Ph: 432-684-6373 Fx: 432-682-1316	LUSK		
4. Location of Well (Footage, Sec., T	R., M., or Survey Description)	0	5 2014 11. County of	or Parish, and State	
Sec 3 T19S R32E NWSE 198	0FSL 1730FEL	AUG 2	5 2014 11. County of LEA CO	DUNTY, NM	
12 CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE 8	OTICE REPORT OR	OTHER DATA	
· · · · · · · · · · · · · · · · · · ·	torium Bon(Es) To			OTTERDATA	
TYPE OF SUBMISSION	·	TYPE O	F ACTION		
Notice of Intent	☐ Acidize	Deepen	☐ Production (Start/Res	sume)   Water Shut-Off	
☐ Subsequent Report	☐ Alter Casing	▼ Fracture Treat	☐ Reclamation	■ Well Integrity	
	Casing Repair	■ New Construction	Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon ☐ Plug Back	☐ Temporarily Abandon ☐ Water Disposal	n	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit. This is notification that new performance will frac 1 stage new performance of the stage of the	nandonment Notices shall be filed nal inspection.)  rforations will be added f/ stations f/ 9170-9180' and c	only after all requirements, includents, i	ing reclamation, have been co	PROVED  UG 19 2018  WANNEGEMENT  OF LAND MANAGEMENT	
	Electronic Submission #25 For MARSHAL	4515 verified by the BLM Wel L & WINSTON INC, sent to the ssing by ED FERNANDEZ on Title OPFRA	e Hobbs	ARL SOND FIFED	
OTILITATE OF THE OTILITATE OTILITATE OF THE OTILITATE OTI	- NODENIO	OF ETO	HONG GEOREIVART		
Signature (Electronic S	ubmission)	Date 07/24/2	014		
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		
Approved By EDWARD FERNANI	DEZ	TitlePETROLE	UM ENGINEER	Date 08/19/2014	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or ertify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		ot warrant or			
Fitle 18 U.S.C. Section 1001 and Title 43 t States any false, fictitious or fraudulent st	J.S.C. Section 1212, make it a createments or representations as to	me for any person knowingly and any matter within its jurisdiction.	willfully to make to any depar	tment or agency of the United	

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

## **Conditions of Approval**

Federal 3 #2 30-025-25701 Marshall & Winston August 19, 2014

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. H2S monitoring equipment to be used on location and functional.
- 4. Must conduct a casing integrity test to max treating pressure before any perforating or frac can be done. Submit results to BLM.
- 5. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 6. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Completion Report and Subsequent sundry with well test and wellbore schematic required within 30 days of completion
- 8. Workover approval is good for 90 days (completion to be within 90 days of approval).

EGF 081914