Form 3160-5 (March 2012)	ĥ	5.1	OCL FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014 5. Lease Serial No. NMNM15015A					
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposate.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well Oil Well		~ 1	AUG 2 9 21	8. 7	Well Name and No)		
2. Name of Operator		Other	11/8		API Well No.	Oakson "A" Federa	ıl #2	
NBI 3a. Address	o tetro	RECEIV			30-005-20617			
P.O. Bo 4470	3b. Phone No. (in 918-488-21		(e) 10. Field and Pool or Exploratory Area Tom Tom (San Andres)					
4. Location of Well (Food	····	11. County or Parish, State						
Unit Letter N: 660' FSL - 1980' FWL Sec 33 - T7S - R31E Chaves County,							M 	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA								
TYPE OF SUBMISSION TYPE OF ACTION								
✓ Notice of Intent	Acidize	Deepen			on (Start/Resume)	Water Shut-Of	f	
	Alter Casi			Reclamat		Well Integrity		
Subsequent Report	Casing Re		Istruction Abandon	Recomple	rily Abandon	Other		
Final Abandonment			-	Water Di	-			
 following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, hay SECONTACH POCKAS determined that the site is ready for final inspection.) (1) MIRU well service unit & circulating tank. Fill with fresh clean treated (bactericide) water. (2) RIH with Notched collar on 2-3/8" work-string (WS) to clean out to PBTD of 3992'. (3) POOH w/same. (4) RIH w/2-3/8" WS & 4-1/2" AD-1 type tension packer to approximately 3800' (Must be no higher than 3788'). Set packer & test backside. If well does not have integrity then test to find bad interval. Make necessary repairs per discussion with Tulsa Engineering Staff. After well will pass pre-test, notify BLM & NMOCD to arrange witnessed test. (5) Perform witnessed MIT with BLM/NMOCD personnel to 500 psig for 1/2 hour. Have circular chart present for permanent record of test. (6) After passing MIT then unseat packer. RIH so end of tubing (EOT) is at 3892'. (7) Spot 1500 gal 15% NEFE acid into annulus. POOH w/WS & packer to 1650'. Close casing valves and squeeze acid into perfs. Overflush using 2 Bbl 2% KCI water. NOTE - SITP. (8) Let acid work for 2 hrs. RIH w/WS & packer to 3845' (+/-). Then begin flow and swab back of load. (9) POOH wWS & packer. (10) RIH w/1 it 2-3/8" tubing bull-plugged as a MA, 1-4'X2-3/8" slotted sub, 2" SN & new 2-3/8" tubing. Put end of MA @ 3830'(+/-). (11) RIH w/2 ig as separator on bottom of 1.5" FHTC pump and straight 3/4" rods and pony rods to seat pump. (12) Long stroke pump with Unit to make sure good pump action. (13) RDMO well service unit and hang well on pump. 								
	foregoing is true and correct. Na			a Engineer				
	ATP. Spencer		itle Sr. Oil & Ga					
Signature	for A server	7	ate 07/21/2014	۱				
		SPACE FOR FEDER	AL OR STAT		EUSE			
Approved by	10/000	al algune	Assis	tant Fie	ld Manage	,		
Approved by ISI Angel Mayes				s And M	linerals	Date 8-27	14	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person k				1		nowell Field Office		
	1 and Title 43 U.S.C. Section 12 ments or representations as to an		on knowingly and v	willfully to m	ake to any departme	int or agency of the Unit	eu States any faise,	
(Instructions on page 2)			_				1. N. N	
						SEP 0 2 20	14] M	

÷.1

`~1

GENERAL INSTRUCTIONS

This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area or regional procedures and practices, are either shown below, will be issued by or may be obtained from the local Federal office.

SPECIFIC INSTRUCTIONS

Item 4 - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

Item 13 - Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to the top of any tubing left in the hole; method of closing top of well and date well site conditioned for final inspection looking for approval of the abandonment.

NOTICES

The Privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq., 25 U.S.C. 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and grantingapproval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as required by 43 CFR 3162.4-1(c)and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3-2, 3162.3-3, 3162.3-4.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM collects this information to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

Response to this request is mandatory.

The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.


BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Collection Clearance Officer (WO-630), 1849 C St., N.W., Mail Stop 401 LS, Washington, D.C. 20240

> JOEBO THMSON OPPORT NOR

LI :01!!! IT ONY HUR

移出公式 5

(Form 3160-5, page 2)



Maciptosh_HD:Users:tammyg:Library:Containers:com.apple.mail:Data:Library:Mail Downloads:2995729F-039C-45BE-868B-49A2A69C8D96:Present - Oakson _A_ Fed #2 Wellbore Diagram.xlsSchematic (1) 7/1/14 Diagram.xlsSchematic (1)

BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.