
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSER	VATION DIVISION	1	1001304 5 27 2001	
DISTRICT I	1220 South St. Francis Dr.		WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240	Santa F	e, NM 87505	30-025-34375		
DISTRICT II			5. Indicate Type of Lease STATE X	FEE	
1301 W. Grand Ave, Artesia, NM 88210 DISTRICT III			6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410			o. State on & Gas Bease 110.		
SUNDRY NO	TICES AND REPORTS ON W	VELLS	7. Lease Name or Unit Agree	ment Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC BACK-TO A			North Hobbs (G/SA) Uni	North Hobbs (G/SA) Unit	
	APPLICATION FOR PERMIT" (Form	C-1011) for such proposals.)	Section 32		
1. Type of Well:	Gas Well Other	SEP 0 8 2014	8. Well No. 542		
Oil Well X 2. Name of Operator		SED 118 5014	9. OGRID No. 157984		
Occidental Permian Ltd.	\		157701		
Address of Operator		RECEIVED	10. Pool name or Wildcat	Hobbs (G/SA)	
HCR I Box 90 Denver City, T2	₹ 79323				
	Foot From The C 4	Line and C20	Foot From The	t in a	
Unit Letter I : 1650	Feet From The South	Line and 630	Feet From The East	_ Line	
Section 32	Township 18-S		38-E NMPM	Lea County	
	11. Elevation (Show whether DF, 3635' GL	RKB, RT GR, etc.)			
Pit or Below-grade Tank Application	or Closure				
· · · · · · · · · · · · · · · · · · ·		n nearest fresh water well	Distance from nearest s	urface water	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
The Delot Glade funk. Volume					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERIN	G CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG &	ABANDONMENT	
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CE			
OTHER:		OTHER:		<u> </u>	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any					
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU.					
2. ND wellhead/NU BOP.					
3. POOH and lay down ESP equipment.					
4. RIH w/bit. Tagged @4460'. POOH w/bit. 5. RIH w/CIBP set @4320'.					
6. RIH w/packer set @4288'. Tested CIBP to 700#. Tested OK. Move packer up hole to 3950'. Tested backside to surface at 600#. Tested					
OK. POOH /packer.					
7. RIH w/ESP equipment set on 121 jts of 2-7/8" tubing. Intake set @3974'. 8. ND BOP/NU wellhead.					
	on and return well to production.				
RUPU 05/21/2014 RDPU 05/28/20	•				
I hereby certify that the information above is		owledge and belief. I further cer	tify that any pit or below-grade tank	has been/will be	
constructed or			·	ז	
closed according to NMOCD guidelines	, a general permit	or an (attached) alternated	ative OCD-approved		
SIGNATURE Mend	a achoron		ive Associate DAT	E 9/4/2014	
TYPE OR PRINT NAME Mendy A	Johnson E-mail address:	mendy johnson@oxy.c			
For State Use Only					
APPROVED BY	MANNE 2	TITLE DEST	Swewson DA	TE 4/9/2014	
CONDITIONS OF APPROVAL IF ANY		11100	CONTRACTOR	" " " " " " " " " " "	

Work Plan Report for Well: NHSAU 542-32



Survey Viewer