Submit 1 Copy To Appropriate District Office District I – (575) 393-6161	State of New N Energy, Minerals and Na		Form C- Revised August 1, 2	
1625 N. French Dr., Hobbs. NM 88240           District II – (575) 748-1283           811 S. First St., Artesia, NM 88210           District III – (505) 334-6178           1000 Rio Brazos Rd., Aztec, NM 87410           District IV. (505) 476 2460	OIL CONSERVATIO 1220 South St. Fr Santa Fe, NM 3	ancis Dr.	WELL API NO. 30-025-03183 5. Indicate Type of Lease STATE FEE XX 6. State Oil & Gas Lease No.	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sunta 1 0, 1 (1)	01000	o. State Off & Gas Lease No.	
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	ES AND REPORTS ON WELL LS TO DRILL OR TO DEEPEN OR P FION FOR PERMIT" (FORM C-101)	LUGBACKADA	7. Lease Name or Unit Agreement Nan East Pearl Queen Unit	ne
1. Type of Well: Oil Well Gas V	Well Other INJECTION		8. Well Number 7	
2. Name of Operator State of New Mexico formerly Xeric (	Dil & Gas Corp.	100 0 1 2011	9. OGRID Number <b>25482</b>	
<ol> <li>Address of Operator</li> <li>1625 N. French Drive Hobbs, New</li> </ol>	Mexico 88240	RECEIVED	10. Pool name or Wildcat Pearl Queen	
4. Well Location				
Unit LetterJ:1980_	feet from theS	line and1980	feet from theEline	
Section 22	Township 19S	Range 35E	NMPM County Lea	
and a second	1. Elevation (Show whether D	R, RKB, RT, GR, etc.		
12. Check App	propriate Box to Indicate	Nature of Notice,	Report or Other Data	

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK       PLUG AND ABANDON         TEMPORARILY ABANDON       CHANGE PLANS         PULL OR ALTER CASING       MULTIPLE COMPL         DOWNHOLE COMMINGLE			TERING CASING 🔲		
OTHER: 13. Describe proposed or completed operations. (Clearl	y state all I	OTHER: pertinent details, and give pertinent dates, in	ncluding estimated date		

of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

## SEE ATTACHMENTS: PROCEDURE & SCHEMATIC

Spud	Date:
------	-------

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Major TITLE_Compliance Officer	DATE 7/5/2013
ype or print name E-mail address:	PHONE: _575-393-6161
APPROVED BY: Mach Whiteham TITLE Compliance Officer	DATE 7/11/2013
Conditions of Approval (if any):	NOV 0 4 2014

State of New Mexico formerlyXERIC OIL & C	GAS
LEASE NAME_ EAST_PEARL QUEEN UNIT	7 API 30-0 25 - 03183
U.L. J Section <u>22</u> -T <u>19</u> S-R <u>35</u> E	from <u>1980</u> æ∕s l, <u>1980</u> e / ₩ l.

**SPECIAL NOTE**—Mud Laden Fluid will consist of 9.5# brine with 12.5# Salt Gel per BBL (25 sacks of gel/ per 100 BBLS Brine). All cement plugs will be 25 sacks of cement or 100', whichever is greater. **Unless otherwise specified in the approved procedure**, cement plugs shall consist of class "C" for depths to 7500'. Class "H" will be used for plugs deeper than 7500'.

- 1. MIRU plugging unit. Lay down production equipment.
- 2. Set CIBP @ 4100'. Circulate MLF. Spot 25 sxs cmt on CIBP. PRESSURE TEST CSG.
- 3. Perf/Sqz or Spot 25 sxs cmt @ 3350 '. If perf, WOC & TAG.
- 4. Perf /Sqz or Spot 25 sxs cmt @ 1750 '. If perf WOC and TAG.
- 5. Perf/Sqz or Spot @ **300** ', w/ sufficient volume to circ cmt to surface inside/outside of csg strings.
- 6. Cutoff wellhead and anchors, install marker.

-----SPECIAL NOTES------

PLUGO	SING & ABANDON	MENT WO	RKSH	EET	T DE ALM	fame	lu Xe	en Aniel	
	<u> </u>	OPERATOR LEASENAME	SIAT CAR		EADI	TUCINEI (DU)EE	MAG	ELC CILZE	3#C
		LEASENAME	END	P	EAEL	WELL		17-	
1	1	SECT	クつ		<b>N I</b>		# 7		
		SECT FROM		TWI Kal/S	IV . •	195	RNG	<u> 226</u>	
		TD:	780	603	-	1980			
		PBTD:	·			ATION			
					FUR	MATION	@Pbj	D	
Rf & SQZ	18 11		SIZE	SI	ET @	TOC		RMINED BY	
X1 7 J42	8% 32	SURFACE	8518			SURF	CIR		
	= <u></u>	INTMED 1	0.0			JUN	Luni		
300 4 1	TOC SURF	INTMED 2							
		PROD	5'12"	4	906	?	7006	X CMT	
77177			SIZE	the second s	OP	BOT		DETERMINED BY	
1750	PEEF'S SQZ	LINER 1		· •	<u> </u>			SPICKATIAN D	
1120	25 SXS CMT	LINER 2							
	23 323 LIII		CUT & I		. @		TOP	- BOTTOM	
		INTMED 1			-9	PERFS		-	
		INTMED 2				OPENHOLE	<u> </u>	-	
	· •	PROD							
		* REQUIRED PLU	IGS DISTRIC	TI				<u></u>	
		RISTLER (ANEYD)		*	PLUG	TYPE	SACKS	DEPTH	
7/////	SPOT 255xs	YATES		1		PLUG	CMNT		
2200'	. CMT	OUEEN		1	EXMOLES				
3350		GRAYEURO	·	1	PLUGII	OH	25 575	9850	
		AN ANDRES		1	FLUG#2	SHOE	50 505	8700-8900	
71777				1	nour	CIBP/35'		5300'	
SET		CAPITAN LEEK		*	FLUDIS	CEP	25 575	53007	
IBPQ ·				1	riva 14	STUB	50 505	4600-4700	
4700'	=4772-4778	DELAWARE		1	1210316	REINR SQ2	200 525	400 '	
$\Delta P \omega / 1$	- 4810 - 4814	BELL CANYON	1	1	FL0017	SURF	10 525	0-10'	
AP ω/ 255xs Cmt	4840 - 4840	CEFET CANYON	1		RUDR				
CMT		BRIDELY CARTON		]	10012				
	اللي اللي السر	BONZ RTAINS	1	]	110015				
	512 15.5,17				PL0314				
	@ 4906'	CLORETA		]*	FLUG #5				
	$     \begin{array}{r}       4772 - 4718 \\       4810 - 4816 \\       4840 - 4846 \\       5\frac{1}{2} 15.5, 17 \\       \underline{0} 4906' \\       TOC ?     \end{array} $	BLREERY			MUX316				
	CMT W/ZOOSKS	TUES		1	PLUGIT	·			1
		DEDITARD			PLUG / I	<u> </u>	- <u> .</u>		Į
	1 <sup>e</sup>	130		_	10019				Į
		[	4	_	PLUGIN				1
		WC		-	uma i				-
		PERR		-	PLUG			·	+
		STRAWN		-1					-
		ATOKA	-	-					-
	TD 4906	VIOLEDOW		-1					-
			_{	-1					4
		OEVORAN	1		l				<b>-1</b>