Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resour	rces May 27, 2004
Office <u>District I</u> 1625 N. French Dr., Hobbs, NM *** ODBS OCD Energy, Minerals and Natural Resources District II		WELL API NO.
<u>District II</u>	OIL CONICEDUATION DIVICIO	ON 30-025-26372 5. Indicate Type of Lease
	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 8750		VC-0018-0001
	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO .	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		GETTY 1 STATE
PROPOSALS.) 1. Type of Well: Oil Well G	as Well Other SWD	8. Well Number 1
2. Name of Operator	JUNE COLOR OVE	9. OGRID Number 024010
V-F PETROLEUM INC.		
3. Address of Operator		10. Pool name or Wildcat
P.O. BOX 1889, MIDLAND, TEXAS	3 79702	EAST GRAMA RIDGE-MORROW
4. Well Location		
Unit Letter F: 1,650 feet from the NORTH line and 1,650 feet from the WEST line		
Section 1	Township 22-S Range 34-E	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,631' RKB		
Pit or Below-grade Tank Application or Closure		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Chec	K Appropriate Box to indicate Nature of Noti	ce, Report of Other Data
NOTICE OF INTE		SUBSEQUENT REPORT OF:
	PLUG AND ABANDON REMEDIA	
	A CHARLES GOLDING	CE DRILLING OPNS. P AND A
PULL OR ALTER CASING OTHER:	MULTIPLE COMPL CASING/O	RETURN WELL TO PRODUCTION
	nerations (Clearly state all pertinent details	RETURN WELL TO PRODUCTION and give partinent dates including estimated date of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
		·
	•	
	(SEE BACK)	
		•
Thereby a d'Called de Called		
grade tank has been/will be constructe	d or closed according to NMOCD guidelines	edge and belief. I further certify that any pit or below- , a general permit or an (attached) alternative
OCD-approved plan 口.	D 1.	
SIGNATURE Sando K.		
Type or print name Sandra K. Lawl	is E-mail address: <u>skl@</u>	vfpetroleum.com Telephone No. (432) 683-3344
(This area of Co. Co.		
(This space for State use)		
APPPROVED BY	TITLE Petroleum Er	igineer I In UhiU
MITTOVED DI	TITLE Petroleum Er	DATEDATE
Conditions of approval if any:	Ajvegene	

RU WSU. Make 1 swb run. No fluid. RD rel WSU. 06/10/14 Well open to test tank. 06/11/14 -06/29/14 MIRU Swbg unit. Make 2 swb runs. Rec 4 ½ bbls wtr. RD rel swbg unit. 06/30/14 07/01/14 -Well open to test tank. 07/18/14 MIRU Swbg unit. Make 2 swb runs. Rec 4 bbls wtr. Lve well open to test tank. RD rel swbg unit. 07/19/14 Well open to test tank. 07/20/14 -08/06/14 MIRU Swbg Unit. Make 5 swb runs. Rec 5 bbls wtr. Lve well open to test tank, RD rel swbg unit. 08/07/14 08/08/14 -Well open to test tank. 08/24/14 MIRU Swbg Unit. Make 4 swb runs. Rec 2 bbls wtr. Lve well open to test tank. RD rel swbg unit, 08/25/14 Well open to test tank. 08/26/14 -09/12/14 09/13/14 MIRU Swbg Unit. Make 2 swb runs. Rec 7 bbls fluid. Wait 1 hr. Make swb run. Rec 1 bbl fluid. Lve well open to test tank. RD & rel swbg unit. 09/14/14 -Well open to test tank. 09/30/14 MIRU Swbg Unit. Swb well 3 hrs. Rec 5 bbls wtr. RD swbg unit. MI & set 2 – 500 bbl frac tanks. 10/01/14 10/02/14 -WO frac job 10/03/14 10/04/14 RU Cudd Services. Frac Morrow perfs 12,820' - 12,830'. Well sanded off @ 12,000#. SD unable to pump in. RD Cudd & all equip. WO coil tbg unit. 10/05/14 -10/20/14 10/21/14 RU flowback manifold. Install flowback manifold. 10/22/14 10/23/14 -WO coil tbg unit. 10/28/14 MIRU Cudd Services coil tbg unit. 10/29/14 10/30/14 Run in hole w/coil tbg. Get sand out of tbg. Pull coil tbg. RD coil tbg unit. MIRU swbg unit. Swb 4 hrs. Rec 6 bbls wtr. 10/31/14

Make 3 swb runs. Rec 4 bbls wtr. RD rel swbg unit. Lve wellopen to flow tank. Start connecting tank bttry.

MIRU swbg unit. Make 4 swb runs. Rec 6 bbls wtr. RD rel swbg unit. Lve well open to flow tank.

Swb 4 hrs. Rec 4 bbls wtr. Lve well open to flow tank.

Connecting tank battery. Well open to flow tank.

Well open to flow tank with slight blow.

Lve well open to flow tank.

11/01/14 11/02/14 -

11/03/14 11/04/14

11/05/14 -

11/11/14

11/12/14 11/13/14 •

11/17/14