
Submit I Copy To Appropriate District Office	State of New Mexico	,		Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resour			ised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL	API NO.	257
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISIO	N S	0-041-10	002
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		cate Type of Lease	77
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE FE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa i e, i vivi 67303	6. State	Oil & Gas Lease N	0.
87505	٠.			
	CES AND REPORTS ON WELLS	7. Leas	e Name or Unit Agr	eement Name
1 '	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	Α		
1	CATION FOR PERMIT" (FORM C-101) FOR SUCH		Neathers b	y
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well	Number 3	
2 Name of Operator		9 OGE	RID Number	
Thomas and	Ruly Parkinson Trust	J. OGI	219023	,
3. Address of Operator	,	10 Poc	ol name or Wildcat	
PD. Box 398 M	Tresand, N.M. 8812	2 5 1 1 ° · · · ° °	Than of Theode	;
10. 100x 310 1111	mes and 11.11.001-	<u> </u>		
4. Well Location	1050	100		
Unit Letter:				line
Section 24	Township 8 S Range 34		County	
	11. Elevation (Show whether DR, RKB, RT, 6	GR, etc.)		
2,500			4.38	
12. Check A	Appropriate Box to Indicate Nature of N	lotice. Report	or Other Data	
22. 0	ppropriate z on to zince i i i i i i i i i i i i i i i i i i i			
NOTICE OF IN	TENTION TO:	SUBSEQUE	ENT REPORT (OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIA	L WORK	🔀 ALTERIN	IG CASING □
TEMPORARILY ABANDON	CHANGE PLANS	ICE DRILĻING OI	PNS.□ P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/0	CEMENT JOB		
DOWNHOLE COMMINGLE	·			
CLOSED-LOOP SYSTEM	·			
OTHER:	OTHER:			
	leted operations. (Clearly state all pertinent de			
	ork). SEE RULE 19.15.7.14 NMAC. For Mult	iple Completions	: Attach wellbore di	iagram of
proposed completion or rec	ompletion.			
	. 🐧 .			:
1. Pulled tubin	y + Pocker	r		• •
2 Bail tdrill				
2. 13 all Facili	to creat vois'			
3 Panlace 4 aints	and added 2 joints of Libring			
	•			•
4. Sat ADI P.	ncker at 4531'			
	•			
5. Put well	back in operation.			
	-1. 1. 9			•
	•			
-				
Spud Date:	Rig Release Date:			•
I hereby certify that the information	above is true and complete to the best of my kr	owledge and hel-	ief.	
Thereby certify that the information	A state and complete to the best of my ki	io wiedge and bei	····	:
	/) 			
SIGNATURE Luy to	ar humo TITLE Manager		DATE <i>10</i>	. 22-2014
		01	<i>f</i> .	
Type or print name _ Terry /	Parkinson E-mail address: Jap	a 060 vah	w.cojRHONE:57	15-441-1256
For State Use Only	() 		— " t	:
	6 1 Shar		٠	
APPROVED BY:	Ornamal TITLE Shar	NaNager	DATE_ <i>_/0/</i>	22/2014
Conditions of Approval (if any):			ė.	· /
• • • • • • • • • • • • • • • • • • • •	FOR RECORD ONLY		DEC-2	A 2018'



FUR RECORD ONLY

BS 10/22/2014