Submit LCopy To Appropriate District	State of New Mexico			Form C-103		
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources			WELLADING	Revised July 18, 2013	7
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OW GOVERNMENT			WELL API NO. 30-025-26186		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of	of Lease	1
<u>District IJI</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.				FEE 🗌	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505			6. State Oil & Ga L2662	s Lease No.	
87505 SUNDRY NOT	TICES AND REPORTS ON	WELLS		7. Lease Name or	Unit Agreement Name	-
(DO NOT USE THIS FORM FOR PROP	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A LICATION FOR PERMIT" (FORM C-101) FOR SUCH			New Mexico 28 State		
1. Type of Well: Oil Well	Gas Well Other HOBBSOCD			8. Well Number 1		
2. Name of Operator Vernon E. Faulconer, INC.	,		3316	9. OGRID Numbe	er 148394]
3. Address of Operator	JAN 1 2 2013			10. Pool name or Wildcat		
1001 ESE Loop 323, Suite 160	P. O. Box 7995 Tyler, Tx 7	5711 .		85210 Shoe Bar; A	Atoka	
4. Well Location		RECE]
<u> </u>	et from the East line and 660) feet from the So	uth line			
Section 28	Township 16S	Range 3		NMPM	County Lea /	4
	11. Elevation (Show when 4,011' RKB	ther DR, RKB, RT	, GR, etc.)			
	1,011 Ideb					J
12. Check	Appropriate Box to Indi	icate Nature of	Notice, R	eport or Other	Data	
	NTENTION TO:		E-PERM	ITTING	-	
PERFORM REMEDIAL WORK	_	⊠ REN	P&A NR		P&AR	
TEMPORARILY ABANDON DULL OR ALTER CASING		☐ CON CAS	INT TO F	284 PM)	COMP	
DOWNHOLE COMMINGLE	=	LI CAS	CSNG		CHG Loc	
CLOSED-LOOP SYSTEM			TA	RBDI	VIS CHART	
OTHER:	1.1.1.(01.1.	OTHL.		· · · · · · · · · · · · · · · · · · ·	<u> </u>	
13. Describe proposed or com	ipleted operations. (Clearly swork). SEE RULE 19.15.7.14					;
proposed completion or re		TOTAL	imple Com	dictions. Attach w	choose diagram of	
	•					
VEE along to get a builded plug above	us the anon norfe and set con	ant plugg par ingt	mustisms the	anahant tha mallha	ana Diagga aga tha	
VEF plans to set a bridge plug above attached abbreviated plugging proc				•	ore. Please see the	
attached accretimed plagging pro-		uiii, uiiu proposoc		.ug.u		
						٠
. •						
0.17		D' D I D .	2.15			
Spud Date: 1/21/79		Rig Release Date	: 3/5/	/9		
I hereby certify that the information	nabove is frue and complete	to the best of my	knowledge	and belief.		-
		_	_		. 1	
SIGNATURE LOGICO	, //	٤.	_		1/1/	
- /A 01	TITLE	e enzine	m_	DA	TE <u>// 8//5</u>	-
Type or print name Loy SLop	7	address: NS_{a}	LOANCE	Vefine. Care H	-1/	2
For State Use Only	7		LOANCE	, , =	-1/	- '2 -
APPROVED BY:	7		er Loance Duper	, , =	-1/	- 2
For State Use Only	7		er LOANCE Duper	, , =	-1/	- - -

Abbreviated Plugging Procedure

Well Name: New Mexico 28 State #1

Field: Shoe Bar

Location: Lea County, NM Objective: Pull casing and P&A

Date: January 7, 2015 **Prepared by:** Will Ross

- Set CIBP in 4 ½" casing @ 12,400'
- Place 25 sack Class H cement plug on top of bridge plug (330') from 12,400' –
 12,070'
- Circulate plugging fluid throughout wellbore until hole is clean and full. Fluid will be 9.5 ppg brine with 12.5 ppb salt gel
- Place 25 sack Class H cement plug (210') in 5 ½" casing from 9,070' 8,860'
- We anticipate to cut the 5 ½" casing at 5,810' and pull that 5 ½" casing out of the wellbore. This depth is subject to change based off of stretch calculations
- Place 38 sack Class C cement plug (100') in 5 ½" casing and in 7 7/8" open hole from 5,860' 5,760' WOC FTAGE OF GO STORE DEPTA
- Place 43 sack Class C cement plug (100') in 7 7/8" open hole and in 9 5/8" casing from 4,918' – 4,818'
- Place 47 sack Class C cement plug (100') in 9 5/8" casing from 3,260' 3,160'
- Place 47 sack Class C cement plug (100') in 9 5/8" casing from 1,900' 1,800'
- Place 47 sack Class C cement plug (100') in 9 5/8" casing from 462' 362' WOC FTAG-
- Place 47 sack Class C cement plug (100') in 9 5/8" casing from 100' Surface

Please note:

- An additional cement plug may be necessary inside the 5 ½" casing above 8,860' depending on where the casing is cut and pulled from. We will not exceed 3,000' between cement plugs. We will place a cement plug 50' above and 50' below the casing stub wherever it is cut
- We will tag the cement plugs as often as instructed by NMOCD
- Cement volumes were calculated assuming a 1.1 ft³/sack yield



TD @ 13,055'

VERNON E. FAULCONER, INC. Downhole Schematic



WELL NAME: New Mexico State 28 #1 FIELD: Shoe Bar (Atoka) API: 30-025-26186 LOCATION: Sec 28- T16S - R35E Lea County, NM DATE: 5 Jan 15 **ELEVATIONS:** GL: 3,990' RKB: 4,011' SPUD DATE: 22 Jan 79 Prepared by: Haley Copeland **CURRENT WELLBORE** NOTE: All depths are RKB unless otherwise noted 13-3/8" 48# csg @ 412' Circulated cmt. 9-5/8" 40# csg @ 4,868' Circulated cmt. 2',4',6',8', pup jts. (403) 2-3/8" 4.7# N-80 EUE 8rd tbg 5-1/2" 17# csg Surface - 11,541' BHS @ 12,444' 1-25/32" SN @ 12,445' EOT @ 12,446' Atoka Perfs: 12,453-82' (30 shots)

4-½" 13.5# N-80 csg 11,541' – 13,055' (3.795" drift) 1050 sxs of LW and H



TD @ 13,055'

VERNON E. FAULCONER, INC. Downhole Schematic



WELL NAME: New Mexico State 28 #1 FIELD: API: 30-025-26186 Shoe Bar (Atoka) LOCATION: Sec 28- T16S - R35E Lea County, NM ELEVATIONS: GL: 3,990' RKB: 4,011' DATE: 7 Jan 15 SPUD DATE: 22 Jan 79 Prepared by: Will Ross PROPOSED WELLBORE 47 sack Class C cmt plug from 100' - Surface NOTE: All depths are RKB unless otherwise noted 47 sack Class C cmt plug from 462' - 362' 13-3/8" 48# csg @ 412' Circulated cmt. 47 sack Class C cmt plug from 1,900' - 1,800' 47 sack Class C cmt plug from 3,260' - 3,160' 43 sack Class C cmt plug from 4,918' - 4,818' 9-5/8" 40# csg @ 4,868' Circulated cmt. 38 sack Class C cmt plug from 5,860' - 5,760' Cut 5 1/2" csg @ 5,810' 25 sack Class H cmt plug from 9,070' - 8,860' 5-1/2" 17# csg Surface - 11,541' 25 sack Class H cmt plug from 12,400' - 12,070' CIBP @ 12,400' Atoka Perfs: 12,453-82' (30 shots)

4-½" 13.5# N-80 csg 11,541' - 13,055' (3.795" drift) 1050 sxs of LW and H