
					OCD-HOBBS		
E SUNDRY Do not use th					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM30400 6. If Indian, Allottee or Tribe Name		
			- MANAN	INEM	· · · · · · · · · · · · · · · · · · ·		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. NM 104037 x			
Type of Well Gas Well Gas Well Other: INJECTION					8. Well Name and No RED HILLS NOR		
2. Name of Operator EOG RESOURCES, INC. Contact: STAN WAGNER E-Mail: stan_wagner@eogresources.com					9. API Well No. 30-025-36584		
a. Address P.O. BOX 2267 MIDLAND, TX 79702	3b. Phone No. (includ Ph: 432-686-3689	No. (include area code) 686-3689		10. Field and Pool, or Exploratory RED HILLS; BONE SPRING			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				1	1. County or Parish,	and State	
Sec 12 T25S R33E SWNE 2213FNL 1920FEL					LEA COUNTY,	NM	
L 12 11 /1 2	4215 - 380W]			
12. CHECK APP	ROPRIATE BOX(ES) TO I	NDICATE NATU	JRE OF NO	DTICE, REP	ORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			CTION			
 Notice of Intent Subsequent Report Final Abandonment Notice 	Subsequent Report Casing Repair		Fracture Treat Reclar New Construction Recon			 Water Shut-Off Well Integrity Other 	
	Convert to Injection	Plug Back			posal		
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for f EOG Resources proposes to 1. POOH w/ tubing. 2. Make up & RIH w/ RBP. So	ork will be performed or provide the d operations. If the operation results bandonment Notices shall be filed final inspection.) repair a casing leak for this	e Bond No. on file wit ts in a multiple comple only after all requirem well as follows:	n BLM/BIA. 1 etion or recomp ents, including	Required subse pletion in a nev	quent reports shall be v interval, a Form 316 lave been completed, SUBJECT	filed within 30 days 0-4 shall be filed once and the operator has	
 Dump 2 sks of sand on top Make up CICR and RIH w/ Squeeze w/ 200 sks Class WOC 24 hours. RIH to drill out cement and Pressure test squeeze to 1 RIH and retreive RBP. Perform MIT test and return 	o of RBP. / CICR to 9120'. Establish in H cement. Sting out of CICI I CICR, wash down to top of 1000 psi.	jection rate thru ho R and reverse circ	ole in 7" cas	ing.		TACHED FOR S OF APPROVAL	
				formation S	ystem		
4. I hereby certify that the foregoing is	Electronic Submission #284	I588 verified by the SOURCES, INC., se	BLM Well In ent to the Ho	bbs			
4. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) STAN WA	Electronic Submission #284 For EOG RES	I588 verified by the SOURCES, INC., se Title	ent to the Ho	bbs ORY ANAL	YST ADD	DAVEN	
	Electronic Submission #284 For EOG RES	SOURCES, INC., se	ent to the Ho	bbs ORY ANAL	APP	ROVED	
Name (Printed/Typed) STAN WA	Electronic Submission #284 For EOG RES	SOURCES, INC., se Title Date	REGULAT 12/09/201	bbs ORY ANAL	APP	ROVED	
	Electronic Submission #28 For EOG RES	SOURCES, INC., se Title Date	REGULAT 12/09/201	bbs ORY ANAL	APP	ROVED	
Name (Printed/Typed) STAN WA Signature (Electronic S	Electronic Submission #28 For EOG RES AGNER Submission) THIS SPACE FOR d. Approval of this notice does not uitable title to those rights in the su	FEDERAL OR	REGULAT 12/09/201	bbs ORY ANAL	APP	AND MANAGEMEN	

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

MOB/OCD 1/20/2015

JAN 2 1 2015

M



.

Conditions of Approval

EOG Resources, Inc. Red Hills North Unit - 213H, API 3002536584 T25S-R33E, Sec 12, 2213FNL & 1920FEL, Surface January 06, 2014

- Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Johnny Chopp
- 2. Before casing or a liner is added, replaced, or repaired prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Use of class "H" cement at depths greater than 7500ft & "C" at depths less than 7500ft will be necessary. Class "C" squeeze cement is be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.
- 5. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 12575 or below to top of cement taken with 0psig casing pressure. The CBL may be attached to a <u>pswartz@blm.gov</u> email. The CFO BLM on call engineer may be reached at 575-706-2779.
- 6. Surface disturbance beyond the existing pad shall have prior approval.
- 7. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 8. Functional H_2S monitoring equipment shall be on location.
- 9. 5000 (5M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Blind ram(s) and pipe ram(s) designed to close on all workstring diameters used is required equipment. A manual BOP closure system (hand wheels) shall be available for use regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 10. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 11. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

12. Submit a subsequent Sundry Form 3160-5 relating the dated daily wellbore and MIT activities. File the form within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.

Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). Verify all annular casing vent valves are open to the surface during this pressure test. An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 4) Make arrangements 24 hours before the test for BLM to witness. In Eddy County email Paul R. Swartz <u>pswartz@blm.gov</u> or phone 575-200-7902, if there is no response, 575-361-2822. In Lea County phone 575-393-3612. If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number.
- 5) Submit a subsequent Sundry Form 3160-5 relating the dated daily wellbore and MIT activities. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 6) Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.
- 7) Submit the original subsequent sundry with three copies to BLM Carlsbad.
- 8) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 9) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.

- 10) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 11) A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.
- 12) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 13) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 14) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0 psia. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902). If there is no response phone 575-361-2822.
- 15) Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of installed equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer. The setting depths and descriptions of each are to be included in the subsequent sundry. List daily descriptions of any previously unreported wellbore workover(s) and reason(s) the well annular fluid was replaced.
- 16) A request for increased wellhead pressures is to be accompanied by a step rate test. <u>PRIOR</u> to a Step Rate Test BLM – CFO is requiring a Notice of Intent.
- 17) CFR 146.13(a)(1) & CFR 146.23(a)(1) Class I wells are permitted stimulation injection pressure to exceed frac pressure while <u>Class II (production water disposal) wells</u> do not have that provision.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.