E SUNDRY Do not use th abandoned we		ERIOR EMENT S ON WELLS ill or to re-enter an for such proposals. ons on reverse side.	JAN 2222015 Lease Serial N NMLC02950 6. If Indian, Allot	Agreement, Name and/or No.	
3a. Address ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701-4287 3b. Phone No. (include area code) Ph: 432-685-4332 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 21 T17S R32E SENW 2160FNL 2310FWL 32.821412 N Lat, 103.772520 W Lon				I, or Exploratory ish, and State IY, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
Attach the Bond under which the wor following completion of the involved	ally or recomplete horizontally, give ck will be performed or provide the l operations. If the operation results bandonment Notices shall be filed or inal inspection.)	e subsurface locations and me Bond No. on file with BLM/ in a multiple completion or nly after all requirements, inc	□ Water Disposal	Well Integrity Other Venting and/or Flari ng ' proximate duration thereof. ertinent markers and zones. I be filed within 30 days 3160-4 shall be filed once	
14. I hereby certify that the foregoing is Committe Name (Printed/Typed) KANICIA (Electronic Submission #2368 For COG OPE d to AFMSS for processing by	BEVERLY WEATHERFC	Vell Information System le Hobbs VRD on 05/02/2014 (14BMW0330S PARER	E)	
Signature (Electronic S	,	Date 02/25	ACCEPTED FOR R	ECORD	
	THIS SPACE FOR I	FEDERAL OR STAT			
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu Title 18 U.S.C. Section 1001 and Title 43 I States any false, fictitious or fraudulent s	itable title to those rights in the subj ct operations thereon. U.S.C. Section 1212, make it a crim	e for any person knowingly a		JEMEN HEE	
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** MUBJOCA 1/26/2015 JAN 26 2015					

¢'

wdB/oca	1/26/	2015
---------	-------	------

Additional data for EC transaction #236827 that would not fit on the form

32. Additional remarks, continued

 32.
 Additional remarks, com

 MC Federal 20 30-025-38703
 MC Federal 21 30-025-38815

 MC Federal 29 30-025-38717
 MC Federal 29 30-025-38998

 MC Federal 30 30-025-39058
 MC Federal 32 30-025-39000

 MC Federal 35 30-025-39107
 MC Federal 36 30-025-39107

 MC Federal 36 30-025-39107
 MC Federal 38 30-025-39107

 MC Federal 36 30-025-39107
 MC Federal 36 30-025-39425

 MC Federal 52 30-025-40152
 MC Federal 54 30-025-39425

 MC Federal 56 30-025-39427
 MC Federal 56 30-025-39427

 MC Federal 63 30-025-39867
 MC Federal 63 30-025-39867

 MC Federal 63 30-025-39867
 MC Federal 66 30-025-39500

June 2013 1990 MCF flared

July 2013 3305 MCF flared

August 2013 2153 MCF flared

September 2013 0 MCF flared

Due to DCP plant acid gas problems.