#### EOG RESOURCES, INC. HAWK 26 FED #1H

### Hydrogen Sulfide Plan Summary

- A. All personnel shall receive proper H2S training in accordance with Onshore Order III.C.3.a.
- B. Briefing Area: two perpendicular areas will be designated by signs and readily accessible.
- C. Required Emergency Equipment:
  - Well control equipment
    - a. Flare line 150' from wellhead to be ignited by flare gun.
    - b. Choke manifold with a remotely operated choke.
    - c. Mud/gas separator
  - Protective equipment for essential personnel.

#### Breathing apparatus:

- a. Rescue Packs (SCBA) 1 unit shall be placed at each breathing area, 2 shall be stored in the safety trailer.
- b. Work/Escape packs —4 packs shall be stored on the rig floor th sufficient air hose not to restrict work activity.
- c. Emergency Escape Packs —4 packs shall be stored in the doghouse for emergency evacuation.

#### Auxiliary Rescue Equipment:

- a. Stretcher
- b. Two OSHA full body harness
- c. 100 ft 5/8 inch OSHA approved rope
- d. 1-20# class ABC fire extinguisher
- H2S detection and monitoring equipment:

The stationary detector with three sensors will be placed in the upper dog house if equipped, set to visually alarm @ 10 ppm and audible @ 14 ppm. Calibrate a minimum of every 30 days or as needed. The sensors will be placed in the following places: Rig floor / Bell nipple / End of flow line or where well bore fluid is being discharged.

(Gas sample tubes will be stored in the safety trailer)

- Visual warning systems.
  - a. One color code condition sign will be placed at the entrance to the site reflecting the possible conditions at the site.
  - b. A colored condition flag will be on display, reflecting the current condition at the site at the time.
  - c. Two wind socks will be placed in strategic locations, visible from all angles.

#### EOG RESOURCES, INC. HAWK 26 FED #1H

#### ■ Mud program:

The mud program has been designed to minimize the volume of H2S circulated to surface. The operator will have the necessary mud products to minimize hazards while drilling in H2S bearing zones.

#### ■ Metallurgy:

All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold and lines, and valves shall be suitable for H2S service.

#### ■ Communication:


Communication will be via cell phones and land lines where available.


## EOG RESOURCES, INC. HAWK 26 FED #1H

## **Emergency Assistance Telephone List**

PUBLIC SAFETY:		911 or	
Lea County Sheriff's De	partment		(575) 396-3611
Rod Coff	man		,
Fire Department:			
Carlsbad			(575) 885-3125
Artesia			(575) 746-5050
Hospitals:			` ,
Carlsbad			(575) 887-4121
Artesia			(575) 748-3333
Hobbs			(575) 392-1979
Dept. of Public Safety/Carlsbad			(575) 748-9718
Highway Department			(575) 885-3281
New Mexico Oil Conser	vation		(575) 476-3440
U.S. Dept. of Labor			(575) 887-1174
EOG Resources, Inc.			·
EOG / Midland		Office	(432) 686-3600
200,1111111111		·	(132) 000 3000
<b>Company Drilling Con</b>	sultants:	•	
Danny Kiser Will Hend		Cell	(432) 894-3417
Larry King		Con	(132) 07 1 3 117
Duriy iting			
Drilling Engineer			
Kirby Castille		Office	(432) 686-3657
,		Cell	(432) 559-4987
Drilling Manager		<b>34</b> 11	(132) 557 1707
Steve Munsell		Office	(432) 686-3609
		Cell	(432) 894-1256
<b>Drilling Superintenden</b>	ıt	2011	(132) 03 1 1230
Ron Welch	.•	Office	(432) 686-3695
TOM WOOM		Cell	(432) 386-0592
Cactus Drilling		Con	(132) 300-0372
Cactus Drilling		Office	(580) 799-2752
Cactus 123 Drilling Rig		Rig	(432) 894-3417
Cuctus 123 Dinning 14g		146	(132) 05 1 3 117
Tool Pusher:			
Jack Herndon		Cell	(405) 519-6552
Larry Slife		Cell	(405) 250-6368
Safety			
Reggie Phillips (HSE Manager)		Office	(432) 686-3747
		Cell	(432) 250-7507
			(.5-) -50 ,501

# **EXHIBIT 2C**RECLAMATION AND FACILITY DIAGRAM - PRODUCTION FACILITIES DIAGRAM





LEASE NAME & WELL NO.: HAWK 26 FED #1H #1H LATITUDE N 32.1825967 #1H LONGITUDE W 103.5489756

LEGEND					
<b>(</b>	500 BBL OIL TANK	©	FLARE SEPARATOR		
$\bigcirc$	500 BBL WATER TANK		VRU		
H H S	36 x 15 HEATER/ SEPARATOR	0	48 X 25 VRT		
	SEPARATOR		FP FLARE		
		6	OP FLARE		