State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION	
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South	St. Francis Dr. NM 87505	WELL API NO. 30-025-07498
DISTRICT II	,		5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	1		STATE FEE X
DISTRICT III	·		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410			·
SUNDRY NO	OTICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		North Hobbs (G/SA) Units OF SOCO	
,	'APPLICATION FOR PERMIT" (Form C-1		Section 31
1. Type of Well: Oil Well	Gas Well Other Te	mporarily Abandoned	8. Well No. 441 / EER 0 5 2015
Name of Operator Occidental Permian Ltd.		inportany redundence	9. OGRID No. 157984
3. Address of Operator			10. Pool name or Wildcat Hobbs (G-SA)
HCR 1 Box 90 Denver City, T	X 79323		a distribution of the state of
4. Well Location			
Unit Letter P : 330	Feet From The South	Fe	et From The <u>East</u> Line
Section 31	Township 18-S	Range 38-	E NMPM Lea County
	11. Elevation (Show whether DF, RK 3635' DF	(B, RT GR, etc.)	
Dit on Delaw and Tank Application	Cleans C		1
Pit or Below-grade Tank Application			
			Distance from nearest surface water
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls; Construction M	aterial
12 Cha	ok-Appropriate Rov.to-Indicate Na	ture of Notice Report or	Other Data
E-PERMITTING	× 114	SUB	SEQUENT REPORT OF:
P&A NR	P&A R		
			I I ALTERIAL CACING I I
		REMEDIAL WORK	ALTERING CASING
INT TO P&A	COMP	REMEDIAL WORK COMMENCE DRILLING OF	
INT TO P&A	C⊙MP CHG Loc	•	PNS. PLUG & ABANDONMENT
INT TO P&A	COMP	COMMENCE DRILLING OF CASING TEST AND CEME	PNS. PLUG & ABANDONMENT NT JOB
INT TO P&A CSNG TA RBDI	COMPCHG LocMS CHART	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integr	PNS. PLUG & ABANDONMENT NT JOB Tity test/TA status request
INT TO P&A CSNG TA RBDI 13. Describe Proposed or Completed C	COMPCHG LocMS CHART	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integrences etails, and give pertinent date	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request x s, including estimated date of starting any
INT TO P&A CSNG TA RBDI 13. Describe Proposed or Completed C	COMP	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integrences etails, and give pertinent date	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request x s, including estimated date of starting any
INT TO P&A CSNG TA 13. Describe Proposed or Completed C proposed work) SEE RULE 110.	COMP CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integree ctails, and give pertinent date rellbore diagram of proposed	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request x s, including estimated date of starting any
13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 Date of test: 01/22/2015	COMP CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integree ctails, and give pertinent date rellbore diagram of proposed	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request x s, including estimated date of starting any
13. Describe Proposed or Completed Coproposed work) SEE RULE 110. Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI:	COMP CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integretails, and give pertinent date rellbore diagram of proposed	PNS. PLUG & ABANDONMENT NT JOB Tity test/TA status request s, including estimated date of starting any completion or recompletion.
13. Describe Proposed or Completed Coproposed work) SEE RULE 1103 Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO	COMP CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integretails, and give pertinent date rellbore diagram of proposed	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request x s, including estimated date of starting any completion or recompletion.
13. Describe Proposed or Completed Coproposed work) SEE RULE 110. Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes	COMP CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integretails, and give pertinent date rellbore diagram of proposed	PNS. PLUG & ABANDONMENT NT JOB Tity test/TA status request s, including estimated date of starting any completion or recompletion.
INT TO P&A CSNG TA 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO CIBP @3875	COMP CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integretails, and give pertinent date rellbore diagram of proposed	PNS. PLUG & ABANDONMENT NT JOB Tity test/TA status request s, including estimated date of starting any completion or recompletion.
INT TO P&A CSNG TA 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO CIBP @3875' Top perf @3939'	CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w 15 min – 530 PSI; 30 min – 530 PS	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integretails, and give pertinent date rellbore diagram of proposed This Ap	PNS. PLUG & ABANDONMENT NT JOB Tity test/TA status request s, including estimated date of starting any completion or recompletion.
INT TO P&A CSNG TA RBDI 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO CIBP @3875' Top perf @3939' Thereby certify that the information above constructed or	CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w 15 min – 530 PSI; 30 min – 530 PS is true and complete to the best of my know	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integretails, and give pertinent date rellbore diagram of proposed This Ap Abando	PNS. PLUG & ABANDONMENT NT JOB Tity test/TA status request s, including estimated date of starting any completion or recompletion. Typroval of Temporary Typroval of Temporary Typroval Expires 1/22/2016 That any pit or below-grade tank has been/will be
INT TO P&A CSNG TA 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI Length of test: 30 minutes Witnessed: NO CIBP @3875' Top perf @3939'	CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w 15 min – 530 PSI; 30 min – 530 PS is true and complete to the best of my know	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integrated in the case of the case	PNS. PLUG & ABANDONMENT NT JOB Tity test/TA status request s, including estimated date of starting any completion or recompletion. Typroval of Temporary Typroval of Temporary Typroval Expires 1/22/2016 That any pit or below-grade tank has been/will be
INT TO P&A CSNG TA RBDI 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO CIBP @3875' Top perf @3939' Thereby certify that the information above constructed or	CHG Loc MS CHART Operations (Clearly state all pertinent do 3. For Multiple Completions: Attach w 15 min – 530 PSI; 30 min – 530 PS is true and complete to the best of my know	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integretails, and give pertinent date rellbore diagram of proposed This Ap Abando	PNS. PLUG & ABANDONMENT NT JOB Pity test/TA status request s, including estimated date of starting any completion or recompletion. Proval of Temporary In that any pit or below-grade tank has been/will be the occupance of the proved that any pit or below-grade tank has been/will be the occupance of the proved that any pit or below-grade tank has been/will be the occupance of the proved that any pit or below-grade tank has been/will be the occupance of the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that any pit or below-grade tank has been/will be the proved that the proved the proved that the proved the proved that the proved the proved that the proved the proved the proved the proved that the proved the proved the proved the proved the proved the
INT TO P&A CSNG TA RBDI 13. Describe Proposed or Completed C proposed work) SEE RULE 1103 Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO CIBP @3875' Top perf @3939' I hereby certify that the information above constructed or closed according to NMOCD guideline SIGNATURE	CHG Loc MS CHART Operations (Clearly state all pertinent de 3. For Multiple Completions: Attach w 15 min – 530 PSI; 30 min – 530 PS 15 is true and complete to the best of my known as peneral permit	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integrate etails, and give pertinent date tellbore diagram of proposed This Ap Abando To an (attached) alternative plan TITLE Administrative	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request s, including estimated date of starting any completion or recompletion. Poroval of Temporary nment Expires 1/22/2016 A that any pit or below-grade tank has been/will be the OCD-approved e Associate DATE 02/04/2015
INT TO P&A CSNG TA CSNG TA RBDI 13. Describe Proposed or Completed C proposed work) SEE RULE 110. Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO CIBP @3875' Top perf @3939' I hereby certify that the information above constructed or closed according to NMOCD guideline SIGNATURE TYPE OR PRINT NAME Mendy A.	CHG Loc MS CHART Operations (Clearly state all pertinent de 3. For Multiple Completions: Attach w 15 min – 530 PSI; 30 min – 530 PS 15 is true and complete to the best of my known as peneral permit	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integretails, and give pertinent date relibore diagram of proposed. This Ap Ab and complete and belief. I further certify or an (attached) alternative plan.	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request s, including estimated date of starting any completion or recompletion. Poroval of Temporary nment Expires 1/22/2016 A that any pit or below-grade tank has been/will be the OCD-approved e Associate DATE 02/04/2015
INT TO P&A CSNG TA RBDI 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO CIBP @3875' Top perf @3939' I hereby certify that the information above constructed or closed according to NMOCD guideline SIGNATURE TYPE OR PRINT NAME Mendy A. For State Use Only	CHG Loc MS CHART Operations (Clearly state all pertinent de 3. For Multiple Completions: Attach w 15 min – 530 PSI; 30 min – 530 PS 15 is true and complete to the best of my known as peneral permit	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integrate etails, and give pertinent date ellbore diagram of proposed. This Ap Abando or an (attached) alternative plan. TITLE Administrative mendy johnson@oxy.com	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request s, including estimated date of starting any completion or recompletion. Poroval of Temporary nment Expires 1/22/2016 A that any pit or below-grade tank has been/will be the OCD-approved e Associate DATE 02/04/2015
INT TO P&A CSNG TA CSNG TA RBDI 13. Describe Proposed or Completed Oproposed work) SEE RULE 110: Date of test: 01/22/2015 Pressure readings: Initial – 540 PSI; Length of test: 30 minutes Witnessed: NO CIBP @3875' Top perf @3939' I hereby certify that the information above constructed or closed according to NMOCD guideline SIGNATURE TYPE OR PRINT NAME Mendy A.	CHG Loc MS CHART Operations (Clearly state all pertinent de 3. For Multiple Completions: Attach w 15 min – 530 PSI; 30 min – 530 PS 15 is true and complete to the best of my known as peneral permit	COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Casing integrate etails, and give pertinent date tellbore diagram of proposed This Ap Abando To an (attached) alternative plan TITLE Administrative	PNS. PLUG & ABANDONMENT NT JOB rity test/TA status request s, including estimated date of starting any completion or recompletion. Poroval of Temporary nment Expires 1/22/2016 A that any pit or below-grade tank has been/will be the OCD-approved e Associate DATE 02/04/2015

FEB 0 9 2015

4.m

