Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAR 0 9 2015

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMNM107395

SUNDRY NOTICES AND REPORTS ON WELLS	~ c.
not use this form for proposals to drill or to re-enter an	J)

Do not use thi abandoned wel	6. If Indian, Allottee or Tribe Name								
SUBMIT IN TRI	erse side.		7. If Unit or CA/Agreement, Name and/or No.						
Type of Well Gas Well □ Oth	8. Well Name and No. FOXGLOVE 29 FEDERAL 7H								
Name of Operator OXY USA INCORPORATED		9. API Well No. 30-025-41851-00-X1							
3a. Address HOUSTON, TX 77210-4294	(include area code 5-5936 -5742	5936 TRIPLE X			itory				
4. Location of Well (Footage, Sec., T	07.12		11. County or Parish, and State						
Sec 29 T23S R33E NENE 340FNL 660FEL 32.281899 N Lat, 103.587466 W Lon					LEA COUNTY, NM				
12. CHECK APPE	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DAT	ΓΑ		
TYPE OF SUBMISSION	TYPE OF ACTION								
☐ Notice of Intent	☐ Acidize ☐ Deep		en 🗖 Produ		ion (Start/Resume)		Vater Shut-Off		
_	☐ Alter Casing ☐ Fra			☐ Reclam	ation	■ Well Integrity			
Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomp	☐ Recomplete		ther		
☐ Final Abandonment Notice	☐ Change Plans ☐ Plug ☐ Convert to Injection ☐ Plug		<u> </u>		arily Abandon	Drilling Operations			
					isposal				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Spud 14-3/4" hole 10/16/14, drill to 1401' 10/17/14. RIH & set 11-3/4" 47# J-55 BTC csg @ 1399', pump 30BFW spacer w/ red dye, then pump 300sx (89bbl) Halcem w/ additives 14.2ppg 1.67 yield, cmt w/ 740sx (228bbl) PPC w/ additives 13.5ppg 1.74 yield followed by 350sx (84bbl) PPC w/ additives 14.8ppg 1.34 yield, circ 673sx (204bbl) cmt to surface, WOC. 10/18/14, Install WH, test to 1050#, test passed. 10/19/14 RU BOP, test @ 250# low 5000# high. Test csg to 2150# for 30min, test passed. RIH & tag cmt @ 1345', drill new formation to 1411', perform FIT test to EMW=13.5ppg, 285psi, good test. 10/19/14 Drill 10-5/8" hole to 5205' 10/22/14. RIH & set 8-5/8" 32# J-55 BTC csg @ 5195', pump 20BFW spacer w/ red dye, then cmt w/ 1070sx (357bbl) PPC w/ additives 12.9ppg 1.87 yield followed by 430sx (102bbl) PPC w/ additives 14.8ppg 1.32 yield, circ 15sx (5bbl) cmt to surface, WOC. Install pack off mandrel, test to 5000#, tested good. 10/24/14, RIH & tag cmt @ 5145', test csg to									
14. I hereby certify that the foregoing is true and correct. Electronic Submission #274373 verified by the BLM Well Information System For OXY USA INCORPORATED, sent to the Hobbs Committed to AFMSS for processing by CHRISTOPHER WALLS on 11/12/2014 (15CRW0025SE)									
Name (Printed/Typed) DAVID S		EGULATORY	,						
Signature (Electronic	Date 10/28/2	2014	· · · · · · · · · · · · · · · · · · ·						
17.	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE				
Approved By ACCEPT	CHRISTO TitlePETROLI	TOPHER WALLS LEUM ENGINEER Date 01/08/2014							
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conditions.	Office Hobbs								
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe to any matter w	rson knowingly an thin its jurisdictior	d willfully to m 1.	ake to any department o	r agency	of the United		

Additional data for EC transaction #274373 that would not fit on the form

32. Additional remarks, continued

2750# for 30 min, test passed. Drill out cement and new formation to 5215', perform FIT test to EMW=11.5ppg (failed), tested EMW=10.1ppg, passed, contacted superintendent & decision was made to drill ahead.